





report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Silver
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Emter.	1
Entry	т.

Elitiy 1	
Date	2021-05-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-02
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #9		2023-07-06 08:28
MOT test	number	293108257614
Result		✓ Passed
Next expi	ry date	2024-08-02
Advice (ii))	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weake	ened edge (1.1.14 (a)
Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))		
Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened edge (1.1.14 (a) (ii))		
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))	
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

MOT #8		2023-07-06 08:28
MOT test	number	291716326421
Result		× Failed
Advice (ii))	Offside Front Inner Brake disc worn, pitted or scored, but not seriously w	eakened edge (1.1.14 (a)
Advice	Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice Rear Coil spring corroded both sides (5.3.1 (b) (i))		
Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened edge (1.1.14 (a) (ii))		
Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))		
Pass wit	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #7 2022-07-08 08:53
MOT test number 720079208742

Result \(\sqrt{Passed} \)

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #6 2021-07-09 09:14

MOT test number 651803270747

Result
✓ Passed

MOT #5 2020-08-03 06:17

MOT test number 543123285197

Result \rightarrow Passed

MOT #4 2019-07-23 07:53

MOT test number 457139046654

Result ✓ Passed

MOT #3 2019-07-22 13:58

MOT test number 984943133691

Result X Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2018-07-26 11:18

MOT test number 685727115361

Result \(\sqrt{Passed} \)

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/12



MOT #1 2017-07-13 09:47

MOT test number 251499618904

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-22
Last registration	2023-07-06
Complete history	See info



Registration #1	2014-07-22	8 mi
Registration #2	2017-07-13	21.550 mi
Registration #3	2018-07-26	28.946 mi
Registration #4	2019-07-22	37.194 mi
Registration #5	2019-07-23	37.194 mi
Registration #6	2020-08-03	41.815 mi
Registration #7		11.777 es
Registration #8		0.074
Registration #9		11.777 es
Registration #10		0.77 44
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles2Engine numberES23713