



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Silver
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-07-04
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-23
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	19
Total items failed	5

MOT #17	2023-08-24 08:48
MOT test number	363798166043
Result	✓ Passed
Next expiry date	2024-08-23
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing slightly damaged (5.2.3 (d) (ii))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake fluid close to minimum mark (1.1.10 (d) (ii))

MOT #16	2022-08-01 08:52
MOT test number	194646855781
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2021-05-04 10:41

**MOT test number**

285637557112

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge 3mm wearing on edges 235 45 17 (5.2.3 (e))

**Advice**

Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge 3mm wearing on edges 235 45 17 (5.2.3 (e))

**Advice**

Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge 3mm wearing on edges 235 45 17 (5.2.3 (e))

**Advice**

Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge wearing on edges 235 45 17 (5.2.3 (e))

**MOT #14**

2020-05-13 10:53

**MOT test number**

328417094493

**Result**

✓ Passed

**Advice**

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice**

ALL FOUR TYRES CRACKING AND PERISHING / WORN ON EDGES - 235 45 17 97W

**Advice**

BOTH REAR BUMP STOP BECOMING DETERIORATED

**MOT #13**

2019-05-07 08:56

**MOT test number**

486317153859

**Result**

✓ Passed

**Advice**

Rear nearside and offside tyres wearing at inner edge

**MOT #12** 2019-05-02 09:27**MOT test number** 177253560538**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear nearside and offside tyres wearing at inner edge**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2018-04-26 10:43**MOT test number** 476303184215**Result** ✓ Passed**Advice** Rear tyres wearing on inner edge**MOT #10** 2017-05-04 13:44**MOT test number** 943775596461**Result** ✓ Passed**MOT #9** 2016-05-10 14:36**MOT test number** 345103814173**Result** ✓ Passed**MOT #8** 2016-05-10 10:22**MOT test number** 965142036103**Result** ✗ Failed**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Registration plate background overprinted or shadowed with text both plates (6.3.1e)



<b>MOT #7</b>	2015-05-05 11:42
<b>MOT test number</b>	655595325111
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2014-05-13 12:20
<b>MOT test number</b>	916233334138
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2013-05-07 16:01
<b>MOT test number</b>	148077123124
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2012-05-14 09:36
<b>MOT test number</b>	205815132166
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2012-02-28 12:43
<b>MOT test number</b>	807509552054
<b>Result</b>	✓ Passed
<b>Advice</b>	Tyre worn close to the legal limit (4.1.E.1)
<b>MOT #2</b>	2011-04-19 09:34
<b>MOT test number</b>	135179501143
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>MOT #1</b>	2010-04-13 16:00
<b>MOT test number</b>	463703000137
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
23 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	23 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-04-17
Last registration	2023-08-24
Complete history	<a href="#">See info</a>



Registration #1	2007-04-17	26 mi
Registration #2	2010-04-13	16.014 mi
Registration #3	2011-04-19	22.613 mi
Registration #4	2012-02-28	24.219 mi
Registration #5	2012-05-14	26.224 mi
Registration #6	2013-05-07	29.725 mi
Registration #7	2014-05-13	33.649 mi
Registration #8	2015-05-05	36.984 mi
Registration #9	2016-05-10	40.862 mi
Registration #10	2016-05-10	40.862 mi
Registration #11	2016-05-10	40.862 mi
Registration #12	2016-05-10	40.862 mi
Registration #13	2016-05-10	40.862 mi
Registration #14	2016-05-10	40.862 mi
Registration #15	2016-05-10	40.862 mi
Registration #16	2016-05-10	40.862 mi
Registration #17	2016-05-10	40.862 mi
Registration #18	2016-05-10	40.862 mi
Registration #19	2016-05-10	40.862 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

NOT KNOWN