



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D4 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	134 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F








Internet history

Entry 1

Date	2021-09-04
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-04-21
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	11
Total items failed	4

MOT #11	2022-04-19 14:30
MOT test number	285223773731
Result	✓ Passed
Next expiry date	2023-04-21
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))

MOT #10	2022-04-19 09:34
MOT test number	739003288518
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))
Fail	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #9	2021-04-22 11:49
MOT test number	325021488838
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2020-09-02 11:14**MOT test number** 274792004649**Result** ✓ Passed**Advice** Offside Front Drag link end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-08-24 14:41**MOT test number** 759458734819**Result** ✓ Passed**MOT #6** 2019-08-24 11:03**MOT test number** 232034422215**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #5** 2018-11-07 15:31**MOT test number** 439273003205**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2018-11-06 10:31**MOT test number** 334928091087**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #3	2017-11-07 15:47
MOT test number	772984017117
Result	✓ Passed
MOT #2	2016-09-22 08:04
MOT test number	740612603573
Result	✓ Passed
MOT #1	2015-09-28 09:50
MOT test number	510947487618
Result	✓ Passed
Advice	Rear Inner Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YE62DYD
Plate since	2024-03-29
Current registration	YE62DYD
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-10-22
Last registration	2022-04-19
Complete history	See info



Registration #1	2012-10-22	25 mi
Registration #2	2015-09-28	25.517 mi
Registration #3	2016-09-22	28.552 mi
Registration #4	2017-11-07	44.417 mi
Registration #5	2018-11-06	58.889 mi
Registration #6	2018-11-07	58.889 mi
Registration #7	2019-08-24	68.788 mi
Registration #8	2019-08-24	68.788 mi
Registration #9	2019-08-24	68.788 mi
Registration #10	2019-08-24	68.788 mi
Registration #11	2019-08-24	68.788 mi
Registration #12	2019-08-24	68.788 mi
Registration #13	2019-08-24	68.788 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1628 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1208964
---------------	---------