



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Black
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-02-05
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-29
Pictures	9
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-03-19
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	63
Total items failed	11

MOT #20	2024-03-20 15:43
MOT test number	156554708896
Result	✓ Passed
Next expiry date	2025-03-19
Advice	Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Underside rusty
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #19**

2023-03-01 15:34

**MOT test number**

862649000812

**Result**

✓ Passed

- Advice** Rear sill areas front cross bars and under body rusty
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Nearside Rear backplate rusty
- Advice** Coolant leak
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #18**

2022-02-23 15:44

**MOT test number**

179037853001

**Result**

✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front cross member rusty
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear back plates rusty

**MOT #17**

2022-02-23 15:44

**MOT test number**

992160072473

**Result**

✗ Failed

- Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front cross member rusty
- Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear back plates rusty

**MOT #16** 2021-02-25 14:21**MOT test number** 240838598595**Result** ✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15** 2021-01-25 11:13**MOT test number** 528064890697**Result** ✓ Passed**MOT #14** 2020-03-04 11:14**MOT test number** 330360199679**Result** ✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Inner Wheel arch liner insecure

**MOT #13**

2020-03-02 17:37

**MOT test number**

399923894819

**Result****✗ Failed****Advice**

Nearside Rear Inner Wheel arch liner insecure

**Fail**

Nearside Rear Anti-roll bar linkage fractured broken in half (5.3.3 (b) (ii))

**Fail**

Emissions not tested (8.2.2.2 (e))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail**

Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

**Fail**

Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values limit 1.0. Blowing over 3.0 (8.2.2.2 (f))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail**

Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12**

2019-02-22 11:25

**MOT test number**

925872632385

**Result****✓ Passed**

**MOT #11**

2017-10-30 10:59

**MOT test number**

668317605152

**Result**

✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Vehicle underside corroded
- Advice** Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Exhaust system corroded

**MOT #10**

2016-10-27 13:28

**MOT test number**

424961751164

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Oil leak at rear diff
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Both rear tyres perished between treads

**MOT #9** 2016-10-27 09:01**MOT test number** 751838112350**Result** ✗ Failed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Oil leak at rear diff
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Both rear tyres perished between treads

**MOT #8** 2015-10-22 07:44**MOT test number** 732918332767**Result** ✓ Passed

- Advice** Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)
- Advice** Exhaust has a minor leak of exhaust gases rear of center box (7.1.2)

**MOT #7** 2014-10-16 10:44**MOT test number** 786529084243**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Notice** Both front tyres bald on edges

**MOT #6** 2013-10-18 12:56**MOT test number** 947231693273**Result** ✓ Passed



**MOT #5** 2012-10-23 12:36**MOT test number** 409647792271**Result** ✓ Passed**MOT #4** 2011-10-20 17:14**MOT test number** 967493191221**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres bald on edges**Notice** Nearside rear tyre low on edge**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-10-20 17:14**MOT test number** 867493491267**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres bald on edges**Pass with rectification** Rear registration plate missing (6.3.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre low on edge**Pass with rectification** Front registration plate missing (6.3.1a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #2** 2010-12-13 16:01**MOT test number** 581997440311**Result** ✓ Passed



MOT #1	2009-11-04 15:16
MOT test number	404728909395
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
19 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	19 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-14
Last registration	2024-03-20
Complete history	<a href="#">See info</a>



Registration #1	2006-09-14	11 mi
Registration #2	2009-11-04	20.364 mi
Registration #3	2010-12-13	24.736 mi
Registration #4	2011-10-20	28.573 mi
Registration #5	2012-10-23	33.575 mi
Registration #6	2013-10-18	39.316 mi
Registration #7	2014-10-16	44.305 mi
Registration #8	2015-10-22	48.476 mi
Registration #9	2016-10-27	53.731 mi
Registration #10	2016-10-27	53.735 mi
Registration #11	2017-10-30	58.647 mi
Registration #12	2018-10-27	63.559 mi
Registration #13	2019-10-27	68.471 mi
Registration #14	2020-10-27	73.383 mi
Registration #15	2021-10-27	78.295 mi
Registration #16	2022-10-27	83.207 mi
Registration #17	2023-10-27	88.119 mi
Registration #18	2024-03-20	93.031 mi
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >





Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1585 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2AD0082158