





report date: 2024-03-28

General information

Make	ТОУОТА
Model	LAND CRUISER D-4D ICON
Colour	Blue
Year of manufacture	2014
Top speed	109 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	420 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.9 mpg
CO2 emission	213 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 3

Date 2023-02-25

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2022-02-11	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

Entry 1

Date	2022-01-05
Pictures	15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-24
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #9	2024-04-17 15:53
MOT test number	178841678725
Result	✓ Passed
Next expiry date	2025-04-24
Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive r bush worn (strong advise) (5.3.4 (a) (i))	movement Damper
Advice Centre to rear exhaust joint corroded	
Advice Both rear shock absorber outer casings corroded	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8		2023-04-25 14:51
MOT test	number	462686693239
Result		✓ Passed
Advice	Nearside Rear Shock outer casing corroded	
Advice	Central Rear Exhaust joint corroded	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2022-11-30 16:13

MOT test number 710460161312

Result ✓ Passed

Advice Central Rear Exhaust Joint Deteriorated and Corroded

Minor Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #6 2022-11-30 16:13

MOT test number 830704186193

Result X Failed

Minor Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Minor Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Central Rear Exhaust Joint Deteriorated and Corroded

MOT #5 2022-01-04 15:03

MOT test number 248248408901

Result ✓ Passed

MOT #4 2020-10-27 12:16

MOT test number 692216519746

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2019-04-30 10:01
MOT test number	983369652124
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))	

MOT #2	2018-04-26 10:36
MOT test number	175498768568
Result	√ Passed
MOT #1	2017-05-03 13:31
MOT test number	997450013518
Result	√ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	NK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



WR14HOH report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-04-30
Last registration	2024-04-17
Complete history	See info



Registration #1	2014-04-30	8 mi
Registration #2	2017-05-03	39.288 mi
Registration #3	2018-04-26	47.323 mi
Registration #4	2019-04-30	52.321 mi
Registration #5	2020-10-27	59.475 mi
Registration #6	2022-01-04	65.502 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1890 mm
Length	4780 mm
Wheel base	2790 mm
Kerb weight	2420 kg
Max. allowed weight	2990 kg

Additional information

Fuel tank capacity	87 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/

Number of axles 2

Engine number 1KD2383495