



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 VTX PLUS HDI
Colour	Black
Year of manufacture	-
Top speed	138 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	370 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history****MOT #18** 2021-03-30 13:50**MOT test number** 321514974206**Result** ✓ Passed**Next expiry date** 2022-03-29**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn outer edge (5.2.3 (e))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))**Advice** Offside Play in steering rack inner joint(s)**MOT #17** 2021-03-29 15:11**MOT test number** 893495380720**Result** ✗ Failed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))**Fail** Offside Rear Suspension unit leaking (5.3.5 (c))**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn outer edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #16** 2020-02-01 13:34**MOT test number** 212368501462**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #15**

2019-02-06 15:08

MOT test number

711404283495

Result

✓ Passed

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #14

2019-02-02 12:17

MOT test number

804558116545

Result

✗ Failed

Fail

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice

Offside Rear Suspension bellows damaged but not to excess (5.3.5 (b) (i))

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail

Offside Front Position lamp not working (4.2.1 (a))

Fail

Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail

Offside Rear Suspension unit leaking (5.3.5 (c))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #13

2018-01-30 15:13

MOT test number

854747342015

Result

✓ Passed

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Nearside Rear Tyre worn close to the legal limit 3mm 215/55*16 (4.1.E.1)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Rear Tyre worn close to the legal limit 3mm 215/55*16 (4.1.E.1)

**MOT #12**

2018-01-30 10:06

MOT test number

595585194317

Result

✗ Failed

- Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Anti-lock braking system component excessively damaged sensor wire broken (3.4.2)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Rear Tyre worn close to the legal limit 3mm 215/55*16 (4.1.E.1)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit 3mm 215/55*16 (4.1.E.1)

MOT #11

2017-02-04 11:46

MOT test number

382271703944

Result

✓ Passed

- Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #10

2016-02-08 15:31

MOT test number

646704123430

Result

✓ Passed

MOT #9

2015-03-11 15:27

MOT test number

129020175467

Result

✓ Passed

**MOT #8** 2015-03-11 13:13**MOT test number** 425480375024**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Headlamp cleaning device inoperative (1.7.2)**Fail** Nearside Rear Fluid suspension unit leaking (2.4.D.2)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2015-03-09 14:07**MOT test number** 569138165019**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Fluid suspension unit leaking (2.4.D.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Headlamp cleaning device inoperative (1.7.2)**MOT #6** 2014-09-09 09:35**MOT test number** 456152754205**Result** ✓ Passed**MOT #5** 2013-09-14 10:36**MOT test number** 627697053232**Result** ✓ Passed**MOT #4** 2012-09-15 10:07**MOT test number** 906679752243**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2012-09-15 10:07**MOT test number** 408529352282**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-09-27 17:14**MOT test number** 959410171214**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-03-04 12:15**MOT test number** 188703261059**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-13
Last registration	2021-03-30
Complete history	See info



Registration #1	2007-09-13	28 mi
Registration #2	2011-03-04	61.184 mi
Registration #3	2011-09-27	73.815 mi
Registration #4	2012-09-15	82.256 mi
Registration #5	2013-09-14	92.848 mi
Registration #6	2014-09-09	101.957 mi
Registration #7	2015-03-09	105.646 mi
Registration #8	2015-03-11	105.651 mi
Registration #9	2015-03-11	105.651 mi
Registration #10	2016-02-08	107.627 mi
Registration #11	2016-02-08	107.627 mi
Registration #12	2016-02-08	107.627 mi
Registration #13	2016-02-08	107.627 mi
Registration #14	2016-02-08	107.627 mi
Registration #15	2016-02-08	107.627 mi
Registration #16	2016-02-08	107.627 mi
Registration #17	2016-02-08	107.627 mi
Registration #18	2016-02-08	107.627 mi
Registration #19	2016-02-08	107.627 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1475 mm
Length	4745 mm
Wheel base	2750 mm
Kerb weight	1576 kg
Max. allowed weight	2055 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ474009721