



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	AMICA CDX
Colour	Blue
Year of manufacture	2008
Top speed	86 mph
0 - 60 mph	18.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	62 BHP
Max. torque	98 Nm at 3.000 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-05
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-19
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	21
Total items failed	3

MOT #18	2023-12-20 12:08
MOT test number	602716499631
Result	✓ Passed
Next expiry date	2024-12-19
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2022-10-27 14:14
MOT test number	573507174104
Result	✓ Passed
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))
Advice	Front Inner Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #16	2021-09-22 14:43
MOT test number	385952224176
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2021-09-22 14:43**MOT test number** 150226097789**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Minor** Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #14** 2020-10-14 14:30**MOT test number** 391096188746**Result** ✓ Passed**Advice** Offside rear tyre has a nail in the tread and is also perishing in tread**Advice** One section of nearside rear side light not working**MOT #13** 2020-10-08 16:36**MOT test number** 845537437028**Result** ✗ Failed**Advice** Offside rear tyre has a nail in the tread and is also perishing in tread**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** One section of nearside rear side light not working**MAJOR** Nearside Front Anti-lock braking system component excessively damaged wheel speed pick up ring cracked (1.6 (e))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps not working (4.7.1 (b) (ii))**MOT #12** 2019-10-05 09:57**MOT test number** 853005411788**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2018-09-28 06:34**MOT test number** 241737273826**Result** ✓ Passed**MOT #10** 2017-10-10 11:23**MOT test number** 547464218058**Result** ✓ Passed**Advice** Nearside Front tyre starting to crack 175/60/13**MOT #9** 2016-06-02 07:53**MOT test number** 443424567254**Result** ✓ Passed**MOT #8** 2016-05-04 12:22**MOT test number** 627003934147**Result** ✗ Failed**Fail** Offside Front Anti-lock braking system component excessively damaged ring (3.4.2)**MOT #7** 2016-02-04 09:46**MOT test number** 808008409993**Result** ✓ Passed**MOT #6** 2016-02-04 09:46**MOT test number** 947883449998**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low and too far to the right. (1.8)



MOT #5 2015-02-10 10:31

MOT test number 497761445021

Result ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #4 2014-02-10 09:19

MOT test number 787631844062

Result ✓ Passed

MOT #3 2013-02-26 12:09

MOT test number 759427553049

Result ✓ Passed

MOT #2 2012-02-20 15:16

MOT test number 939931952020

Result ✓ Passed

MOT #1 2011-02-24 14:25

MOT test number 327625751044

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
19 December 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-04
Last registration	2023-12-20
Complete history	See info



Registration #1	2008-03-04	29 mi
Registration #2	2011-02-24	31.318 mi
Registration #3	2012-02-20	38.022 mi
Registration #4	2013-02-26	42.380 mi
Registration #5	2014-02-10	44.206 mi
Registration #6	2015-02-10	46.151 mi
Registration #7	2016-02-04	48.419 mi
Registration #8	2016-02-04	48.419 mi
Registration #9	2016-05-04	48.750 mi
Registration #10	2016-06-02	48.750 mi
Registration #11	2016-06-02	48.750 mi
Registration #12	2016-06-02	48.750 mi
Registration #13	2016-06-02	48.750 mi
Registration #14	2016-06-02	48.750 mi
Registration #15	2016-06-02	48.750 mi
Registration #16	2016-06-02	48.750 mi
Registration #17	2016-06-02	48.750 mi
Registration #18	2016-06-02	48.750 mi
Registration #19	2016-06-02	48.750 mi
Registration #20	2016-06-02	48.750 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	946 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	G4HG7M201559