





report date: 2024-03-29

### General information

| Make                | FORD                |
|---------------------|---------------------|
| Model               | S-MAX TITANIUM TDCI |
| Colour              | Grey                |
| Year of manufacture | 2014                |
| Top speed           | 120 mph             |
| 0 - 100 km/h        | 10.9 seconds        |
| 0 - 60 mph          | 10.9 seconds        |
| Gearbox             | 6 speed automatic   |

### Engine & fuel consumption

| Power                   | 103 kW / 140 HP / 138 BHP |
|-------------------------|---------------------------|
| Max. torque             | 320 Nm at 1.750 rpm       |
| Engine capacity         | 1.997 сс                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 38.2 mpg                  |
| Consumption extra urban | 54.3 mpg                  |
| Consumption combined    | 47.1 mpg                  |
| CO2 emission            | 149 g/km                  |
| CO2 label               | F                         |



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



| B 4   | $\sim$ $-$  |      |        |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic  | tory   |
| 101   | C I         | 1115 | I OI V |
|       | •           |      | ,      |

| MOT expiry date    | 2024-12-13 |
|--------------------|------------|
| MOT pass rate      | 78 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 2          |
| Total advice items | 25         |
| Total items failed | 0          |

| MOT #9  | 2023-12-13 09:15 |
|---|------------------|
| MOT test number   | 688555809176     |
| Result  | ✓ Passed         |
| Next expiry date  | 2024-12-13       |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (e)) |                  |

| MOT #8          | 2022-12-14 16:13 |
|-----------------|------------------|
| MOT test number | 824607551631     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/12



SL14WKK

report date: 2024-03-29

MOT #7 2022-12-06 12:54

MOT test number 178455643209

**Result** X Failed

MAJOR Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (e))

**MAJOR** Electronic braking system warning device indicates a fault parking brake fault (1.7 (b))

**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge worn more (5.2.3 (e))

**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #6 2021-11-30 14:56

MOT test number 347232902664

Result 

Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**MOT #5** 2020-12-11 10:24

**MOT test number** 628680793775

**Result** 
✓ Passed

MOT #4 2019-05-16 12:16

**MOT test number** 734229132935

Result ... Passed

CarCheck.co.uk page 4/12



MOT #3 2019-05-16 08:51

MOT test number 203325888810

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Nearside Front Service brake lagging in operation (1.2.1 (d))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #2** 2018-05-01 13:09

**MOT test number** 811272518489

Result \( \sqrt{Passed} \)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Engine cover and undertrays fitted

**MOT #1** 2017-04-27 14:03

MOT test number 968049217532

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



#### Tax & MOT check



| Tax status       | Valid until 1 February |
|------------------|------------------------|
| Days left        | 278                    |
| MOT expiry date  | 13 December 2024       |
| Full MOT history | See MOT history        |

#### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



| Owner history  |             |
|--|-------------|
| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report |             |
|  |             |
|  |             |
|  |             |
|  |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Current registration   | AIR<br>AIR  |
| Plate since  |             |
| Current registration   |             |
| Flate since  |             |
|  | More info > |
|  |             |

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 10/12



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 11         |
| First mileage registration | 2014-05-20 |
| Last registration          | 2023-12-13 |
| Complete history           | See info   |



| Registration #1  | 2014-05-20 | 12 mi     |
|------------------|------------|-----------|
| Registration #2  | 2017-04-27 | 24.990 mi |
| Registration #3  | 2018-05-01 | 34.177 mi |
| Registration #4  | 2019-05-16 | 59.210 mi |
| Registration #5  | 2019-05-16 | 59.210 mi |
| Registration #6  | 2020-12-11 | 60.704 mi |
| Registration #7  |            | 0.777 es  |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 9.777 es  |
| Registration #10 |            | 71.777 66 |
| Registration #11 |            | 11.317 es |

More info >

CarCheck.co.uk page 11/12



## Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 |                 |
| 50482 |                 |
| 50501 |                 |
| 60566 |                 |
| 60567 |                 |
| 60569 |                 |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 2154 mm |
|---------------------|---------|
| Height              | 1658 mm |
| Length              | 4768 mm |
| Wheel base          | 2850 mm |
| Kerb weight         | 1688 kg |
| Max. allowed weight | 2505 kg |

### Additional information

| Fuel tank capacity                | 70 I             |
|-----------------------------------|------------------|
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 7 page 12/:      |

Number of axles2Engine numberET47075