



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY DSG
Colour	Black
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	131 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-08-28
Pictures	46
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-08
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	4
Total items failed	4

MOT #9 2024-04-09 08:48

MOT test number 182694603827

Result ✓ Passed

Next expiry date 2025-04-08

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear excessive (5.3.4 (a) (i))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear excessive (5.3.4 (a) (i))

MOT #8 2023-02-03 13:15

MOT test number 388227160546

Result ✓ Passed

MOT #7 2023-02-03 10:27

MOT test number 670348552686

Result ✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6 2022-02-09 09:41

MOT test number 463796568938

Result ✓ Passed

**MOT #5** 2022-02-08 10:56**MOT test number** 740979953407**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #4** 2021-02-23 10:32**MOT test number** 703201932746**Result** ✓ Passed**MOT #3** 2019-11-20 16:13**MOT test number** 218718363137**Result** ✓ Passed**MOT #2** 2018-11-26 12:39**MOT test number** 456000446041**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2017-11-27 09:24**MOT test number** 607710660209**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	EF64AYL
Plate since	2020-03-28
Current registration	EF64AYL
Plate since	2020-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-12-30
Last registration	2024-04-09
Complete history	See info



Registration #1	2014-12-30	23 mi
Registration #2	2017-11-27	40.331 mi
Registration #3	2018-11-26	52.597 mi
Registration #4	2019-11-20	64.320 mi
Registration #5	2021-02-23	78.050 mi
Registration #6	2022-05-20	91.777 mi
Registration #7	2023-05-20	105.504 mi
Registration #8	2024-05-20	119.231 mi
Registration #9	2025-05-20	132.958 mi
Registration #10	2026-05-20	146.685 mi
Registration #11	2027-05-20	160.412 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFFBK81075