






report date: 2024-03-28

## General information

Make	HYUNDAI
Model	1800 CRDI SE
Colour	Black
Year of manufacture	2015
Top speed	104 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	343 Nm at 1.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	197 g/km
CO2 label	



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-09-09

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## MOT history

MOT expiry date	2024-10-17
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	4
Total items failed	9

MOT #11	2023-10-04 15:35
MOT test number	560726911393
Result	<b>✓</b> Passed
Next expiry date	2024-10-17

MOT #10	2022-10-17 12:03
MOT test number	498840974087
Result	✓ Passed

MOT #9	2022-10-10 10:58
MOT test number	675793778135
Result	<b>×</b> Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #8	2021-10-18 14:43
MOT test number	290152620803
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



all lamps (4.7.1 (b) (ii))

MA15VUH

report date: 2024-03-28

MOT #7 2021-10-16 11:42

**MOT test number** 766735777942

Result × Failed

Fail Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #6** 2021-03-10 13:40

**MOT test number** 768646720004

Result \square Passed

MOT #5 2021-03-10 10:58

**MOT test number** 761030924020

**Result** X Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #4 2020-03-10 10:25

**MOT test number** 453290684713

Result 

Passed

MOT #3 2020-03-10 10:25

**MOT test number** 481533173270

**Result** X Failed

Pass with rectification Nearside Rear Registration plate lamp inoperative in the case of a single lamp or

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2 2019-03-04 17:09

**MOT test number** 599266784877

**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge 215/70/16c (5.2.3 (e))

Advice Rear underfloor air conditioning pipe slight leak of oil

MOT #1 2018-03-16 15:33

**MOT test number** 415075188461

**Result** ✓ Passed

CarCheck.co.uk page 5/12



MA15VUH
report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	17 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

#### Owner history

o milet matery	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
********	
***************************************	
********	
***************************************	
************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-31
Last registration	2023-10-04
Complete history	See info



Registration #1	2015-03-31	8 mi
Registration #2	2018-03-16	24.829 mi
Registration #3	2019-03-04	32.966 mi
Registration #4	2020-03-10	41.838 mi
Registration #5	2020-03-10	41.838 mi
Registration #6	2021-03-10	50.930 mi
Registration #7	2021-03-10	50.930 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12




report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

## Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



## Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2238 kg
Max. allowed weight	3030 kg

# Additional information

Fuel tank capacity	75 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	8	page 12/12

Number of axles 2

**Engine number** D4CBE573132