



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA S
Colour	Grey
Year of manufacture	-
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg





Internet history

Entry 1

Date	2021-08-28
Pictures	4
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2020-12-29 10:38
MOT test number	655939129481
Result	✓ Passed
Next expiry date	2021-12-28

MOT #16	2020-12-27 18:32
MOT test number	720024351844
Result	✗ Failed
DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #15	2019-08-01 10:15
MOT test number	736275746429
Result	✓ Passed

MOT #14	2019-07-31 11:57
MOT test number	478165094316
Result	✗ Failed
MAJOR Nearside Rear Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))	
MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Rear Exhaust has a major leak of exhaust gases exhaust blow middle/rear (6.1.2 (a))	
DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

**MOT #13** 2018-12-14 12:10**MOT test number** 672606855443**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Undertrays and engine covers fitted unable to check certain items**MOT #12** 2017-12-12 10:49**MOT test number** 432152291892**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Possible fuel leak from fuel filler neck rear**Advice** Nearside Rear Tyre worn close to the legal limit is 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Under trays and engine covers fitted unable to check certain items**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-11-17 13:35**MOT test number** 958273780674**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit is 2mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit is 3mm (4.1.E.1)**Advice** Undertrays and engine covers fitted unable to check certain items**Advice** Offside Rear Tyre worn close to the legal limit is 2mm (4.1.E.1)

**MOT #10** 2016-01-09 09:48**MOT test number** 841171592679**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-12-29 09:54**MOT test number** 276203764397**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #8** 2013-12-30 10:58**MOT test number** 887814363345**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-12-27 09:50**MOT test number** 528062162310**Result** ✓ Passed**MOT #6** 2012-01-09 12:53**MOT test number** 889089402086**Result** ✓ Passed



MOT #5	2011-01-10 10:59
---------------	------------------

MOT test number	978390511025
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2010-01-11 10:48
---------------	------------------

MOT test number	633951410020
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2009-01-12 10:54
---------------	------------------

MOT test number	950342719059
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #2	2008-01-14 11:59
---------------	------------------

MOT test number	632564918062
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2007-01-08 10:47
---------------	------------------

MOT test number	403118007006
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-01-15
Last registration	2020-12-29
Complete history	See info



Registration #1	2004-01-15	11 mi
Registration #2	2007-01-08	22.470 mi
Registration #3	2008-01-14	28.773 mi
Registration #4	2009-01-12	35.093 mi
Registration #5	2010-01-11	40.986 mi
Registration #6	2011-01-10	45.716 mi
Registration #7	2012-01-09	49.524 mi
Registration #8	2012-12-27	53.243 mi
Registration #9	2013-12-30	57.302 mi
Registration #10	2014-12-29	60.943 mi
Registration #11	2015-01-01	60.943 mi
Registration #12	2015-01-01	60.943 mi
Registration #13	2015-01-01	60.943 mi
Registration #14	2015-01-01	60.943 mi
Registration #15	2015-01-01	60.943 mi
Registration #16	2015-01-01	60.943 mi
Registration #17	2015-01-01	60.943 mi
Registration #18	2015-01-01	60.943 mi
Registration #19	2015-01-01	60.943 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

Engine number	233084
---------------	--------