




report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ TDVI SPORT PREMIUM
Colour	Grey
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-02
Pictures	35
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-07
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	36
Total items failed	10

MOT #20	2024-02-08 11:30
MOT test number	816072994860
Result	✓ Passed
Next expiry date	2025-02-07
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Nail in tyre

MOT #19	2024-01-24 12:31
MOT test number	851413069337
Result	✗ Failed
Fail	Suspension system inoperative (5.3.5 (a))
Fail	Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Rear Oil leak, but not excessive diff (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Offside Front Nail in tyre
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #18** 2023-01-30 17:38**MOT test number** 794097907600**Result** ✓ Passed**MOT #17** 2021-10-26 16:37**MOT test number** 223803612508**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both n/s and o/s (5.2.3 (e))**Advice** Light surface corrosion throughout underside of vehicle.**MOT #16** 2021-10-26 16:37**MOT test number** 476759035310**Result** ✗ Failed**Advice** Light surface corrosion throughout underside of vehicle.**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both n/s and o/s (5.2.3 (e))**MOT #15** 2021-04-13 09:39**MOT test number** 571616453846**Result** ✓ Passed**MOT #14** 2020-10-16 09:30**MOT test number** 549444902504**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))**Advice** Offside Undertray not fully secure (8.1.1 (b) (i))

**MOT #13** 2019-09-19 08:50**MOT test number** 792419194466**Result** ✓ Passed**Advice** Both front tyres wearing outer edges**Advice** Direction indicator slightly discoloured Both rear (4.4.3 (a))**MOT #12** 2018-10-17 14:24**MOT test number** 581430732849**Result** ✓ Passed**MOT #11** 2018-05-01 13:07**MOT test number** 765617458986**Result** ✓ Passed**MOT #10** 2017-06-23 11:24**MOT test number** 610186034119**Result** ✓ Passed**Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Rear Brake pipe slightly corroded upper at chassis and fuel tank (3.6.B.2c)**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #9** 2017-06-22 09:28**MOT test number** 114879774118**Result** ✗ Failed

- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Rear Brake pipe slightly corroded upper at chassis and fuel tank (3.6.B.2c)
- Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Offside Rear Brake hose ferrule excessively corroded (3.6.B.4e)
- Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #8 2016-06-30 08:28**MOT test number** 891639099062**Result** ✓ Passed**MOT #7** 2016-06-13 09:19**MOT test number** 840865505412**Result** ✗ Failed

- Fail** Anti-lock braking system warning lamp does not illuminate (3.4.1b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Rear brake application uneven (3.7.B.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Centre Exhaust has a minor leak of exhaust gases offside at clamp (7.1.2)

**MOT #6** 2015-06-11 14:09**MOT test number** 785632265150**Result** ✓ Passed**Notice** Front tyres cracking on side wall badly but no cords visible**Notice** Rear tyres cracking on side walls but no cords visible**MOT #5** 2014-06-09 15:58**MOT test number** 905340364156**Result** ✓ Passed**MOT #4** 2013-07-22 12:06**MOT test number** 309873403263**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-07-23 12:26**MOT test number** 158705002255**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2011-07-26 17:29**MOT test number** 769957601237**Result** ✓ Passed**Notice** Offside front tyre has sidewall damage and is almost bald on inner edge**Notice** Nearside front tyre has sidewall damage**Notice** Offside rear tyre has a large cut in the sidewall



MOT #1	2011-04-18 13:21
MOT test number	466198601175
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	BK08EOE
Plate since	2024-03-28
Current registration	BK08EOE
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-04-23
Last registration	2024-02-08
Complete history	See info



Registration #1	2008-04-23	6 mi
Registration #2	2011-04-18	25.080 mi
Registration #3	2011-07-26	26.212 mi
Registration #4	2012-07-23	39.729 mi
Registration #5	2013-07-22	53.447 mi
Registration #6	2014-06-09	61.738 mi
Registration #7	2015-06-11	72.315 mi
Registration #8	2016-06-13	80.564 mi
Registration #9	2016-06-30	80.944 mi
Registration #10	2017-06-22	85.470 mi
Registration #11	2017-06-23	85.475 mi
Registration #12	2018-06-20	90.557 mi
Registration #13	2018-06-20	90.557 mi
Registration #14	2018-06-20	90.557 mi
Registration #15	2018-06-20	90.557 mi
Registration #16	2018-06-20	90.557 mi
Registration #17	2018-06-20	90.557 mi
Registration #18	2018-06-20	90.557 mi
Registration #19	2018-06-20	90.557 mi
Registration #20	2018-06-20	90.557 mi
Registration #21	2018-06-20	90.557 mi
Registration #22	2024-02-08	90.557 mi

More info >



Dimensions & weight

Width	1898 mm
Height	1455 mm
Length	5090 mm
Wheel base	3034 mm
Kerb weight	1659 kg
Max. allowed weight	2283 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	03035337G