





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	White
Year of manufacture	2014
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2022-04-27
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	12
Total items failed	12

MOT #11	2021-04-28 11:23
MOT test number	404739357514
Result	✓ Passed
Next expiry date	2022-04-27

MOT #10	2021-04-28 11:03
MOT test number	821129826120
Result	X Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #9	2020-12-21 17:35
MOT test number	944448331879
Result	√ Passed

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT #8 2020-12-16 13:02 948894749541 **MOT** test number Result × Failed Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Fail Offside Front Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii)) **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Sidewall. (5.2.3 (d) (i)) **Advice** Offside Rear Nail in tyre Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail **Advice** Front Exhaust mounting defective (6.1.2 (a))

MOT #7	2019-12-05 15:06
MOT test number	595404378676
Result	✓ Passed

MOT #6		2019-12-02 13:19
MOT test	number	873908016855
Result		🗙 Failed
Advice	Offside Front Wiper smearing screen slightly	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Fail	earside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2019-03-08 08:34

MOT test number 836683915979

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2019-03-07 10:42

MOT test number 454872092562

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #3 2018-01-11 09:58

MOT test number 883595829380

Result \(\sqrt{Passed} \)

Advice Tyre worn close to the legal limit 3.0mm (4.1.E.1)

MOT #2 2018-01-08 13:58

MOT test number 305908881675

Result X Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Tyre worn close to the legal limit 3.0mm (4.1.E.1)

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2017-01-12 16:51

MOT test number 701401071267

Result ✓ Passed

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax expired: 26 December 2020

X MOT

Expired: 27 April 2022

Tax status	Expired at 26 December 2020
Days left	1220 days too late
MOT expiry date	27 April 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owners did this have? Check it in the premium report and see all owner registrations. Download the full report here	

More i	info >
Plate changes	

See in this check if this CITROEN had different number plates. obser of plates Plate since

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-04
Last registration	2021-04-28
Complete history	See info



Registration #1	2014-03-04	22 mi
Registration #2	2017-01-12	47.426 mi
Registration #3	2018-01-08	51.116 mi
Registration #4	2018-01-11	51.540 mi
Registration #5	2019-03-07	55.574 mi
Registration #6	2019-03-08	55.575 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		m.m.

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3136684

CarCheck.co.uk page 12/12