





report date: 2024-03-28

General information

Make	FORD
Model	RANGER WILDTRAK 4X4 DCB TDCI
Colour	Orange
Year of manufacture	2018
Top speed	108 mph
0 - 100 km/h	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	147 kW / 200 HP / 197 BHP
Max. torque	470 Nm at 1.500 rpm
Engine capacity	3.198 cc
Cylinders	5
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.7 mpg
CO2 emission	228 g/km
CO2 label	L



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date 2021-09-25

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-09-24

Pictures 46

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date 2021-08-31

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2024-08-28
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #6	2023-08-29 14:40
MOT test number	639642048453
Result	✓ Passed
Next expiry date	2024-08-28

MOT #5		2022-08-24 16:04
MOT test	number	408559065455
Result		✓ Passed
Advice	Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a	a) (ii))
Advice	Front Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2022-08-24 10:55 **MOT** test number 770416054301 Result × Failed **Advice** Front Brake disc worn, but not excessively Lipped (1.1.14 (a) (i)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) **Advice** Front Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i)) Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) **Advice** Ad-Blue light on dash

MOT #3

MOT test number

Result

MOT #2

2021-09-28 07:37

702897198188

2021-07-22 09:53

MOT test number 404058339082

Result Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2021-07-22 09:53

MOT test number 945126727636

Result ★ Failed

Pass with rectification Nearside Side repeater not working (4.4.1 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	28 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-09-26
Last registration	2023-08-29
Complete history	See info



Registration #1	2018-09-26	25 mi
Registration #2	2021-07-22	29.002 mi
Registration #3	2021-07-22	29.002 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	86%
Pedestrian	81%
Safety systems	71%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1815 mm
Length	5362 mm
Wheel base	3220 mm
Kerb weight	2117 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2
Engine number JJ78571