





General information	
Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI BITURBO S/S
Colour	Silver
Year of manufacture	2018
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G



source: cargurus.co.uk

ry 1			
te	2021-11	-13	
ctures	6		
isting price	<u>View re</u> g	port	
AutoTrader	AutoTrader		
Highly Rated	Highly Rated		FINANCE YOUR NEXT CAR
FOR OUR CUSTOMER	FOR OUR CUSTOMER	Cver 2/O - Frevenses. Venat Alternative Negative Statt: Good Intelection of cars, way purchase, largerphilog grand with track its most in the sampleted do website protor is collectioned and a sub- website protor is collectioned and a sub- stationed and a sub- methylectioned and a sub- stationed and a sub- s	MotoNovo
SERVICE 2021	SERVICE 2020	by warranty tool they wand it undersides the work POC as a good will gestore. Can't thekk them enough. Many the 2005/2021	First Response motion



MOT history

MOT expiry date	2025-02-13
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	7
Total items failed	3

MOT #7		2024-02-01 15:43
MOT test	number	464497531755
Result		✓ Passed
Next expi	ry date	2025-02-13
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))		ooth sides (1.1.14 (a)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn low (5.2.3	(e))

МОТ #6	2024-02-01 09:03	
MOT test number	754198130592	
Result	🗙 Failed	
Advice Front Service brake fluctuating, but not excessively (1	1.2.1 (e))	
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))		
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn low (5.2.3 (e))		

МОТ #5	2023-02-08 08:49
MOT test number	708389195363
Result	✓ Passed





MOT #4	2022-02-14 10:23	
MOT test number	675943978439	
Result	✓ Passed	
MOT #3	2022-02-14 08:33	
MOT test number	855252760891	
Result	🗙 Failed	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))		
MOT #2	2021-03-11 14:14	
MOT test number	667738053403	
Result	✓ Passed	
MOT #1	2021-03-11 14:14	
MOT test number	618711752077	
Result	🗙 Failed	
Pass with rectification Windscreen washer not working (3.5 (a))		



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 13 February 2025
Tax status	Valid until 1 February
Days left	279
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-29
Last registration	2024-02-01
Complete history	See info



Registration #1	2018-03-29	10 mi
Registration #2	2021-03-11	65.397 mi
Registration #3	2021-03-11	65.397 mi
Registration #4		11.777 esi
Registration #5	2022-02-14	72.116 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Safety ratings

NCAP rating	****	1 June of
Adult	52%	EURO
Children	91%	
Pedestrian	53%	
Safety systems	57%	
Overall rating	61%	
Video	see crash video	



Dimensions & weight	
Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1760 kg
Max. allowed weight	2950 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	R9M D4 - C294720LQI