



report date: 2024-03-29

General information

Make	ABARTH
Model	595 595 COMPETIZIONE
Colour	White
Year of manufacture	2016
Top speed	140 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	177 BHP
Max. torque	250 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2024-02-01
Pictures	21
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-05-24
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-13
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	22
Total items failed	11

MOT #10	2024-02-14 14:55
MOT test number	295494430750
Result	✓ Passed
Next expiry date	2025-02-13
Advice	Rear silencer outer skin corroded
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front seat difficult to tilt forward



MOT #9

2024-02-07 16:14

MOT test number

143780697131

Result

✗ Failed

- Advice

Front Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))
- Fail

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice

Offside Front Outer door handle slightly insecure/damaged but still operational
- Fail

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice

Offside Front seat difficult to tilt forward
- Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice

Offside Front daytime running light inop
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Rear silencer outer skin corroded

**MOT #8** 2023-12-19 21:14**MOT test number** 149225153594**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))**Advice** Exhaust back box excessively corroded but not leaking**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Fail** Rear Brake disc significantly and obviously worn both (1.1.14 (a) (i))**MOT #7** 2023-02-04 11:44**MOT test number** 528789970656**Result** ✓ Passed**MOT #6** 2023-02-04 10:10**MOT test number** 818148330684**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #5** 2022-02-07 10:18**MOT test number** 256695924857**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #4** 2021-01-13 14:51**MOT test number** 195226530692**Result** ✓ Passed**MOT #3** 2020-01-27 14:04**MOT test number** 489576338377**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #2** 2020-01-27 08:47**MOT test number** 928080874831**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #1** 2019-02-05 08:15**MOT test number** 604761478953**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
13 February 2025

Tax status		Valid until 1 February
Days left		278
MOT expiry date		13 February 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-04-15
Last registration	2024-02-14
Complete history	See info



Registration #1	2016-04-15	13 mi
Registration #2	2019-02-05	20.720 mi
Registration #3	2020-01-27	24.746 mi
Registration #4	2020-01-27	24.746 mi
Registration #5	2021-01-13	28.642 mi
Registration #6	2022-02-07	33.530 mi
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		
Registration #12		
Registration #13		

More info >



Dimensions & weight

Width	1627 mm
Height	1485 mm
Length	3660 mm
Wheel base	2300 mm
Kerb weight	1070 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	2105700