





report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	34.0 mpg
Consumption combined	28.0 mpg
CO2 emission	276 g/km
CO2 label	М



CarCheck.co.uk page 1/13



OV57EKP report date: 2024-03-29

Internet history

Entry 1

Date	2021-07-08
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-21
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	8
Total items failed	8

MOT #19	2023-12-01 15:01
MOT test number	917995360593
Result	✓ Passed
Next expiry date	2024-12-21

MOT #18		2023-12-01 15:01
MOT test number		582764338237
Result		× Failed
Pass with rectification	Front Headlamp aim too low Both (4.1.2 (a))	

MOT #17		2022-12-22 15:02
MOT test	number	787154245661
Result		✓ Passed
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



Result

OV57EKP

report date: 2024-03-29

✓ Passed

MOT #16	2022-12-21 13:18
MOT test number	738625355059
Result	≍ Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2021-12-02 12:31
MOT test number	333769313990
Result	✓ Passed
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #14	2020-11-24 16:11
MOT test number	866367239138
Result	✓ Passed
MOT #13	2019-11-25 16:44
MOT test number	527277246572
Result	✓ Passed
MOT #12	2018-11-19 13:16
MOT test number	816008734274

MOT #11	2017-11-25 13:15
MOT test number	391178531800
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10	2016-11-26 09:14
MOT test number	460539063512
Result	✓ Passed
MOT #9	2015-11-28 08:40
MOT test number	837300854808
Result	✓ Passed
MOT #8	2014-11-27 14:10
MOT test number	925391134388
Result	✓ Passed
MOT #7	2013-11-22 12:33
MOT test number	748516623321
Result	✓ Passed
MOT #6	2013-11-22 12:33
MOT test number	756436723302
Result	× Failed
Pass with rectification Offside Headlamp aim too high (1.8)	

MOT #5	2012-10-15 11:46
MOT test number	366639482229
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT test number
765604882275

Result

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Parking brake: efficiency below requirements (3.7.C.1b)

 MOT #3
 2011-10-10 09:33

 MOT test number
 517983081262

 Result
 ✓ Passed

 MOT #2
 2011-10-06 14:35

 MOT test number
 755009371289

 Result
 X Failed

Fail Hazard warning switch insecure (1.4.B.1d)

Fail Offside Track rod end has had excessive heat applied (2.2.C.1e)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Nearside Track rod end has had excessive heat applied (2.2.C.1e)

 MOT #1
 2010-09-28 10:40

 MOT test number
 512741370240

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



OV57EKP report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



OV57EKP report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		N

	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-27
Last registration	2023-12-01
Complete history	See info



2007-09-27	28 mi
2010-09-28	17.598 mi
2011-10-06	26.660 mi
2011-10-10	26.661 mi
2012-10-10	34.365 mi
2012-10-15	34.365 mi
2013-11-22	42.681 mi
2014-11-27	50.169 mi
2015-11-28	57.772 mi
2016-11-26	65.550 mi
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	11.777 es
	2010-09-28 2011-10-06 2011-10-10 2012-10-15 2013-11-22 2014-11-27 2015-11-28 2016-11-26

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2229 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles2Engine number883173