



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Red
Year of manufacture	2010
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-03-04
Pictures	18
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-02-15
MOT pass rate	100 %
MOT passed	13
Failed MOT tests	0
Total advice items	37
Total items failed	0

MOT #132024-02-08 15:42

MOT test number594669030639

Result✓ Passed

Next expiry date2025-02-15

- Advice** Front Sub-frame corroded but not seriously weakened very poor condition (5.3.3 (b) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened very poor condition (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #12**

2023-02-03 09:16

MOT test number

114833476247

Result

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Centre exhaust sleeve corroded.
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11

2022-02-05 09:16

MOT test number

455439299794

Result

✓ Passed

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2021-01-25 13:40**MOT test number** 804131972434**Result** ✓ Passed**MOT #9** 2020-02-03 16:08**MOT test number** 656917979362**Result** ✓ Passed**MOT #8** 2019-01-23 11:16**MOT test number** 151939907590**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2018-02-16 12:55**MOT test number** 889709844647**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Nail in tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**MOT #6** 2017-01-23 13:17**MOT test number** 940383227224**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Advice** Covers under vehicle

**MOT #5** 2016-02-08 13:35**MOT test number** 105058319918**Result** ✓ Passed**Advice** Covers under vehicle**MOT #4** 2015-01-21 12:28**MOT test number** 217271225063**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Under-trays fitted obscuring some underside components

MOT #3 2014-01-30 14:46**MOT test number** 169200634087**Result** ✓ Passed**MOT #2** 2013-11-05 15:25**MOT test number** 568349603370**Result** ✓ Passed**MOT #1** 2013-02-20 16:43**MOT test number** 175451753059**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VU10MYD
Plate since	2019-06-29
Current registration	 VU10MYD
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-10
Last registration	2024-02-08
Complete history	See info



Registration #1	2010-03-10	19 mi
Registration #2	2013-02-20	14.812 mi
Registration #3	2013-11-05	17.832 mi
Registration #4	2014-01-30	17.838 mi
Registration #5	2015-01-21	23.249 mi
Registration #6	2016-02-08	30.491 mi
Registration #7	2017-01-23	33.282 mi
Registration #8	2018-02-16	37.260 mi
Registration #9	2019-03-20	39.377 mi
Registration #10	2020-03-20	41.377 mi
Registration #11	2021-03-20	43.377 mi
Registration #12	2022-03-20	45.377 mi
Registration #13	2023-03-20	47.377 mi
Registration #14	2024-03-20	49.377 mi
Registration #15	2025-03-20	51.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1070 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CGG 231658