






General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date


2021-06-05

3

Pictures

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	27
Total items failed	8

MOT #12		2023-08-03 09:31
MOT test number		678797441575
Result		✓ Passed
Next expiry date		2024-08-07
Advice Oil leak, but	t not excessive oil filter leaking (8.4.1 (a) (i))	
Advice Offside Rea	ar Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i	i))
Advice Rear Exhau	ist has a minor leak of exhaust gases Back box section (6.	1.2 (a))

MOT #112023-08-03 09:31MOT test number819671449173Result× FailedAdviceOil leak, but not excessive oil filter leaking (8.4.1 (a) (i))AdviceRear Exhaust has a minor leak of exhaust gases Back box section (6.1.2 (a))AdviceOffside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))Pass with rectificationNearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10	2022-08-08 08:04
MOT test number	170862643377
Result	✓ Passed





MOT #9	2021-07-12 12:00
MOT test number	637427790902
Result	✓ Passed
MOT #8	2020-07-30 14:27
MOT #8 MOT test number	2020-07-30 14:27 906800661220

MOT #7	2020-07-29 12:01
MOT test number	672454053871
Result	🗙 Failed
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))	

MOT #6		2019-09-23 10:25
MOT test	number	492215637933
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Nail in tyre	
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	



SD640LG report date: 2024-03-28

MOT #5	2019-09-23 10:25
MOT test number	510412069387
Result	🗙 Failed
Advice Offside Rear Nail in tyre	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Pass with rectification Offside Headlamp aim projected beam image is obviously inco	orrect (4.1.2 (c))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #4	20	18-09-26 11:46
MOT test	number	491546144640
Result		✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))	
Advice	Daytime running lamps not working not applicable for test due to vehicle age	
Advice	Offside Front indicator lamp unit damaged	

МОТ #3	2018	-09-26 11:46
MOT test number	98	6245268794
Result		🗙 Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Daytime running	lamps not working not applicable for test due to vehicle age	
Advice Front Registration	n plate deteriorated but not likely to be misread damaged (0.1 (b))	
Advice Offside Front inc	licator lamp unit damaged	



SD640LG	
report date: 2024-03-28	3

MOT #2	2017-09-29 14:00
MOT test number	181311052370
Result	✓ Passed
Advice Items removed from driver's view prior to test	
MOT #1	2017-09-29 11:32
MOT test number	234674427562
Result	🗙 Failed
Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its stru	ucture (4.1.D.1b)
Advice Items removed from driver's view prior to test	
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its st	tructure (4.1.D.1b)
Fail Rear brake excessively fluctuating (3.7.B.3)	



Tax & MOT check

√ Taxed	√ мот
Tax due: 1 April 2025	Expires: 7 August 2024
Tax status	Valid until 1 April
Days left	338
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



SD640LG report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-30
Last registration	2023-08-03
Complete history	See info



Registration #1	2014-09-30	14 mi
Registration #2	2017-09-29	19.912 mi
Registration #3	2017-09-29	19.912 mi
Registration #4	2018-09-26	29.491 mi
Registration #5	2018-09-26	29.491 mi
Registration #6	2019-09-23	37.706 mi
Registration #7	2019-09-23	37.706 mi
Registration #8		11.777 est
Registration #9		11.777 mi
Registration #10		11.777 est
Registration #11		
-		
Registration #12		11,117 44
Registration #12 Registration #13		11.517 est 11.517 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	0798077