



**EAIOWCZ**

report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC TDCI
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg






Internet history

Entry 1

Date	2021-07-05
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #11** 2020-10-26 13:14**MOT test number** 703954735276**Result** ✓ Passed**Next expiry date** 2021-10-25**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-10-10 10:31**MOT test number** 395818411925**Result** ✓ Passed**MOT #9** 2018-10-22 10:55**MOT test number** 169592831561**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #8** 2017-10-25 13:39**MOT test number** 400929037938**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #7**

2017-10-25 09:28

**MOT test number**

451088761273

**Result****✗ Failed****Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Items removed from driver's view prior to test**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #6**

2016-09-19 13:14

**MOT test number**

667538406256

**Result****✓ Passed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5**

2016-09-12 11:23

**MOT test number**

882328677881

**Result****✗ Failed****Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Driver's seat insecure (6.2.A.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #4** 2015-09-09 15:34**MOT test number** 606862001009**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-07-30 11:16**MOT test number** 167801414253**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-07-22 09:14**MOT test number** 975513904256**Result** ✗ Failed**Fail** Bonnet cannot be secured in the closed position (8.4.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-11-14 15:12**MOT test number** 658838713388**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-07-30
Last registration	2020-10-26
Complete history	<a href="#">See info</a>



Registration #1	2010-07-30	24 mi
Registration #2	2013-11-14	88.272 mi
Registration #3	2014-07-22	106.665 mi
Registration #4	2014-07-30	107.275 mi
Registration #5	2015-09-09	140.027 mi
Registration #6	2016-09-12	147.196 mi
Registration #7	2016-09-19	147.447 mi
Registration #8	2019-05-29	151.277 mi
Registration #9	2019-05-29	151.277 mi
Registration #10	2019-05-29	151.277 mi
Registration #11	2019-05-29	151.277 mi
Registration #12	2019-05-29	151.277 mi
Registration #13	2019-05-29	151.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1505 kg
Max. allowed weight	2150 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	AM40965
---------------	---------