



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Grey
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-03-06
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-30
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #12	2023-10-09 09:12
MOT test number	202006970440
Result	✓ Passed
Next expiry date	2024-10-30

MOT #11	2023-10-09 09:12
MOT test number	257602804868
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #10	2022-10-31 17:05
MOT test number	114499237468
Result	✓ Passed

MOT #9	2021-07-20 10:36
MOT test number	166958220425
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Under shields fitted
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



<b>MOT #8</b>	2020-07-29 13:09
<b>MOT test number</b>	300926634830
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Rear most seats stowed at time of testing
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #7</b>	2020-07-29 09:28
<b>MOT test number</b>	872519947824
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp aim too low (4.1.2 (a))
<b>MAJOR</b>	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Rear Rear most seats stowed at time of testing
<b>MAJOR</b>	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

<b>MOT #6</b>	2019-08-01 08:33
<b>MOT test number</b>	273747781185
<b>Result</b>	✓ Passed
<b>Advice</b>	Covers fitted

<b>MOT #5</b>	2018-07-25 09:26
<b>MOT test number</b>	567471309460
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2017-07-31 08:05**MOT test number** 574837584449**Result** ✓ Passed**Advice** Vehicle has covers fitted unable to see certain testable items**Advice** Offside rear tyre is old perished and cracked on outer sidewall**Advice** Offside front tyre is worn on inner tread**MOT #3** 2016-08-01 08:47**MOT test number** 683526520250**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear tyre has Hi-Low spots inner edge**Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Rear Passenger seat(s) missing at time of test rear seats folded away preventing full inspection of belts**Advice** Offside Rear tyre perished**MOT #2** 2015-07-28 13:39**MOT test number** 146899805231**Result** ✓ Passed**MOT #1** 2014-08-12 15:00**MOT test number** 476624824265**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
30 October 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	30 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VK61VNB</b>
Plate since	2019-06-29
Current registration	 <b>VK61VNB</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-30
Last registration	2023-10-09
Complete history	<a href="#">See info</a>



Registration #1	2011-09-30	26 mi
Registration #2	2014-08-12	38.537 mi
Registration #3	2015-07-28	40.721 mi
Registration #4	2016-08-01	43.423 mi
Registration #5	2017-07-31	46.173 mi
Registration #6	2018-07-25	49.867 mi
Registration #7	2019-08-01	53.973 mi
Registration #8	2020-08-01	58.079 mi
Registration #9	2021-08-01	62.185 mi
Registration #10	2022-08-01	66.291 mi
Registration #11	2023-08-01	70.397 mi
Registration #12	2024-03-28	74.503 mi
Registration #13	2024-03-28	78.609 mi
Registration #14	2024-03-28	82.715 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1544 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	CAY E79368