





report date: 2024-03-29

#### General information

Make	AUDI
Model	A2 TDI (90BHP)
Colour	Silver
Year of manufacture	2005
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	90 BHP
Max. torque	229 Nm at 1.900 rpm
Engine capacity	1.390 сс
Cylinders	3
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	65.7 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/15



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-10-23

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

## MOT history

MOT expiry date	2024-10-02
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	20
Total items failed	16

MOT #25		2023-10-03 13:53
MOT test	number	454429801137
Result		✓ Passed
Next expiry date 2024-10-0		2024-10-02
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #24	2023-10-03 10:03
MOT test number	695449492554
Result	<b>X</b> Failed
Fail Headlamp aim unable to be tested (4.1.2 (b))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Headlamp levelling device inoperative (4.1.5 (a))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #23	2022-08-22 12:08
MOT test number	677036807002
Result	✓ Passed
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/15



report date: 2024-03-29

**MOT #22** 2021-08-04 16:15

**MOT test number** 424813666819

Result \rightarrow Passed

**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

Advice Offside Front Door hinge slightly insecure, door can still be readily opened and closed

**MOT #21** 2021-08-04 08:17

MOT test number 381540166118

Result X Failed

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

**Advice** Offside Front Door hinge slightly insecure, door can still be readily opened and closed

Fail Nearside Headlamp aim projected beam image is obviously incorrect Bulb incorrectly fitted (4.1.2 (c))

MOT #20 2020-07-30 15:31

MOT test number 601344761633

**MOT #19** 2020-07-24 14:21

MOT test number 298460954700

**Result** ★ Failed

**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #18** 2019-07-19 16:09

**MOT test number** 157027190631

**Result** ✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #17** 2019-07-19 09:11

**MOT test number** 480453345042

**Result** X Failed

Fail Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

MOT #16 2018-07-30 16:21

MOT test number 423451515406

Result 

Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2018-07-30 09:40

**MOT test number** 449195485449

Result X Failed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

MOT #14 2017-07-17 09:20

**MOT test number** 937561121470

**Result** 
✓ Passed

**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #13 2016-08-01 16:12

**MOT test number** 873955931000

**Result** ✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-29

**MOT #12** 2016-08-01 09:49

MOT test number 175784271534

Result × Failed

**Fail** Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #11** 2015-07-27 10:41

**MOT test number** 147028705295

**Result** ✓ Passed

MOT #10 2014-07-25 13:11

**MOT test number** 359326104410

**Result** ✓ Passed

MOT #9 2013-08-09 13:31

**MOT test number** 475011523251

Result \( \sqrt{Passed} \)

**Notice** Front tyres wearing outer edges

MOT #8 2013-08-06 13:49

MOT test number 936088013226

**Result** X Failed

**Fail** Nearside Stop lamp not working (1.2.1b)

**Notice** Front tyres wearing outer edges

**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #7 2012-08-09 12:22

**MOT test number** 338902822269

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #6 2011-08-08 15:58

**MOT test number** 769900021213

MOT #5 2011-08-08 12:42

**MOT test number** 126080121201

**Result** X Failed

Fail Exhaust emits an excessive level of metered smoke for a non-turbo charged engine (7.4.B.3b)

**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #4 2010-07-23 17:04

MOT test number 521354900209

**Result** 
✓ Passed

**Notice** Front brake disc(s) worn

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2010-07-23 11:38

MOT test number 340424900499

**Result** ★ Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Notice** Front brake disc(s) worn

**Fail** Nearside Stop lamp not working (1.2.1b)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2009-08-05 10:00

**MOT test number** 754117619216

Result 

Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #1 2008-08-06 09:10
MOT test number 282959018273

**Result** ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	2 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

$\sim$	1 1 1
Owner	nistory
O WILCI	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>have the premium report and see all owner registrations.</u>	
********	
***************************************	
***************************************	
***************************************	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-08-09
Last registration	2023-10-03
Complete history	See info



Registration #1	2005-08-09	21 mi
Registration #2	2008-08-06	15.657 mi
Registration #3	2009-08-05	21.210 mi
Registration #4	2010-07-23	25.473 mi
Registration #5	2010-07-23	25.473 mi
Registration #6	2011-08-08	30.856 mi
Registration #7	2011-08-08	30.856 mi
Registration #8	2012-08-09	36.979 mi
Registration #9	2013-08-06	45.178 mi
Registration #10	2013-08-09	45.178 mi
Registration #11	2014-07-25	52.279 mi
Registration #12	2016-08-01	72.654 mi
Registration #13	2016-08-01	72.654 mi
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		11.777 es
Registration #17		91.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.117 es
Registration #23		11.777 es
Registration #24		D.777 es
Registration #25		11.777 es
Registration #26		11.777 es

CarCheck.co.uk page 14/15



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	1673 mm
Height	1553 mm
Length	3826 mm
Wheel base	2405 mm
Kerb weight	895 kg
Max. allowed weight	1545 kg

## Additional information

Fuel tank capacity	42 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 15/15

Number of axles 2

Engine number ATL 005658