



report date: 2024-03-28

General information

Make	VOLVO
Model	C70 S 170
Colour	Blue
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	230 Nm at 4.400 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	40.4 mpg
Consumption combined	29.4 mpg
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-06-02
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-19
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #17	2024-04-25 09:56
MOT test number	643349502013
Result	✓ Passed
Next expiry date	2025-05-19

MOT #16	2023-05-20 12:44
MOT test number	397772018303
Result	✓ Passed

MOT #15	2022-05-18 10:17
MOT test number	573826348468
Result	✓ Passed

MOT #14	2021-07-19 09:57
MOT test number	681601033459
Result	✓ Passed

MOT #13	2021-07-16 15:26
MOT test number	314394354910
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

**MOT #12** 2020-11-20 09:49**MOT test number** 177916622991**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside front tyre outer sidewall cut**MOT #11** 2019-05-22 11:51**MOT test number** 542773427968**Result** ✓ Passed**MOT #10** 2018-04-23 08:06**MOT test number** 929363274391**Result** ✓ Passed**MOT #9** 2017-03-30 07:17**MOT test number** 258501964688**Result** ✓ Passed**MOT #8** 2017-03-29 14:16**MOT test number** 616809997191**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #7** 2016-03-14 14:26**MOT test number** 257789506566**Result** ✓ Passed



<b>MOT #6</b>	2015-04-27 16:10
---------------	------------------

<b>MOT test number</b>	956197915129
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2014-04-29 09:05
---------------	------------------

<b>MOT test number</b>	519429414160
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2013-04-22 10:05
---------------	------------------

<b>MOT test number</b>	979982613107
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2012-04-18 10:40
---------------	------------------

<b>MOT test number</b>	428689002164
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-04-28 11:13
---------------	------------------

<b>MOT test number</b>	599318111198
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-04-22 10:57
---------------	------------------

<b>MOT test number</b>	204322410105
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	SMALL CUT IN N/S/F/TYRE SIDEWALL
---------------	----------------------------------

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 August 2024

✓  
**MOT**

**Expires:**  
19 May 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	19 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>SR07EEV</b>
Plate since	2024-03-28
Current registration	 <b>SR07EEV</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-05-28
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	2007-05-28	21 mi
Registration #2	2010-04-22	14.598 mi
Registration #3	2011-04-28	18.524 mi
Registration #4	2012-04-18	21.863 mi
Registration #5	2013-04-22	25.264 mi
Registration #6	2014-04-29	29.091 mi
Registration #7	2015-04-27	31.988 mi
Registration #8	2016-03-14	34.569 mi
Registration #9	2017-03-29	37.014 mi
Registration #10	2017-03-30	37.014 mi
Registration #11	2018-03-29	39.595 mi
Registration #12	2019-03-29	42.176 mi
Registration #13	2020-03-29	44.757 mi
Registration #14	2021-03-29	47.338 mi
Registration #15	2022-03-29	49.919 mi
Registration #16	2023-03-29	52.500 mi
Registration #17	2024-03-29	55.081 mi
Registration #18	2025-03-29	57.662 mi
Registration #19	2026-03-29	60.243 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

**Engine number**

4215652