



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | TOURAN S 5 STR |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 111 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 100 BHP |
| Max. torque | 148 Nm at 3.800 rpm |
| Engine capacity | 1.595 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 25.4 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 34.9 mpg |
| CO2 emission | 193 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-04-21 |
| Pictures | 3 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-06 |
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 27 |
| Total items failed | 6 |

MOT #152023-07-07 09:33

MOT test number440410982279

Result✓ Passed

Next expiry date2024-07-06

- MinorOffside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- AdviceRear Registration plate deteriorated but not likely to be misread (0.1 (b))
- AdviceRear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- AdviceFront Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MinorNearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- AdviceRear Axle swivel pins and bushes swivel pin and/or bush slightly worn both sides (5.1.2 (b) (ii))
- AdviceRear end corroded
- AdviceSuspension component corroded but not seriously weakened front & rear (5.3.3 (b) (i))

**MOT #14**

2023-07-07 09:33

MOT test number

443967011012

Result**✗ Failed****Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both sides (5.1.2 (b) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Suspension component corroded but not seriously weakened front & rear (5.3.3 (b) (i))**Advice** Rear end corroded**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2022-05-12 12:17

MOT test number

178798414009

Result**✓ Passed****MOT #12**

2022-05-10 11:46

MOT test number

632645619055

Result**✗ Failed****Fail** Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #11** 2021-06-19 08:00**MOT test number** 730374445113**Result** ✓ Passed**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #10** 2020-06-26 08:43**MOT test number** 628797785807**Result** ✓ Passed**Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #9** 2019-06-26 08:58**MOT test number** 504982626297**Result** ✓ Passed**Advice** Suspension arm corroded but not seriously weakened front and rear. (5.3.3 (b) (i))**Advice** Full undertrays fitted.**MOT #8** 2018-07-02 08:30**MOT test number** 302588857329**Result** ✓ Passed**Advice** Full undertrays fitted.**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2017-07-07 12:21**MOT test number** 993138836484**Result** ✓ Passed**Advice** Under trays fitted.**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2016-07-06 13:34**MOT test number** 305029308729**Result** ✓ Passed**MOT #5** 2016-07-06 10:53**MOT test number** 625033790322**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #4** 2015-07-03 08:46**MOT test number** 418514485189**Result** ✓ Passed**MOT #3** 2014-07-02 11:26**MOT test number** 597933284116**Result** ✓ Passed**MOT #2** 2014-07-01 09:55**MOT test number** 208912884457**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Fuel cap/sealing device sealing washer missing (7.2.4c)**MOT #1** 2013-07-04 14:51**MOT test number** 205475383470**Result** ✓ Passed**Notice** Both rear tyres cracking within tread.



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
6 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 6 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  SW10FWH |
| Plate since | 2019-06-29 |
| Current registration |  SW10FWH |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2010-07-09 |
| Last registration | 2023-07-07 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-07-09 | 24 mi |
| Registration #2 | 2013-07-04 | 18.332 mi |
| Registration #3 | 2014-07-01 | 24.214 mi |
| Registration #4 | 2014-07-02 | 24.245 mi |
| Registration #5 | 2015-07-03 | 30.591 mi |
| Registration #6 | 2016-07-06 | 36.905 mi |
| Registration #7 | 2016-07-06 | 36.906 mi |
| Registration #8 | 2017-07-07 | 43.525 mi |
| Registration #9 | 2018-07-02 | 49.116 mi |
| Registration #10 | 2019-07-02 | 55.777 mi |
| Registration #11 | 2019-07-02 | 55.777 mi |
| Registration #12 | 2019-07-02 | 55.777 mi |
| Registration #13 | 2019-07-02 | 55.777 mi |
| Registration #14 | 2019-07-02 | 55.777 mi |
| Registration #15 | 2019-07-02 | 55.777 mi |
| Registration #16 | 2019-07-02 | 55.777 mi |
| Registration #17 | 2019-07-02 | 55.777 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2066 mm |
| Height | 1635 mm |
| Length | 4391 mm |
| Wheel base | 2677 mm |
| Kerb weight | 1468 kg |
| Max. allowed weight | 2140 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |

| | |
|-----------------|------------|
| Number of seats | 7 |
| Engine number | BSE 925471 |