





report date: 2024-03-28

General information

| Make | VOLVO |
|---------------------|---------------------------------------|
| Model | V90 INSCRIPTON D4 AUTO D4 INSCRIPTION |
| Colour | - |
| Year of manufacture | - |
| Top speed | 140 mph |
| 0 - 60 mph | 8.2 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 62.8 mpg |



CarCheck.co.uk page 1/8



Internet history

Entry 4

| Date | 2023-06-05 | |
|---------------|--------------------|--|
| Pictures | 0 | |
| Listing price | <u>View report</u> | |

source: carcraft.co.uk

Entry 3

| Date | 2023-03-22 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: carcraft.co.uk

Entry 2


| Date | 2022-11-14 | |
|---------------|-------------|--|
| Pictures | 0 | |
| Listing price | View report | |

source: carcraft.co.uk

Entry 1

| Date | 2022-01-15 |
|---------------|-------------|
| Pictures | 37 |
| Listing price | View report |









source: autotrader.co.uk

CarCheck.co.uk page 2/8



SV18KWL

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 3/8



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 4/8



Owner history

| Owner history | | |
|--|-----------|---|
| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | |) |
| manage of the same | | |
| *************************************** | | |
| *************************************** | | |
| ******** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this VOLVO had different number plates. | | |
| Number of plates | | 9 |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 5/8



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 6/8



Mileage check

| Mileage registrations | 4 |
|-----------------------|----------|
| Complete history | See info |



| Registration #1 | 11.777 es |
|-----------------|-----------|
| Registration #2 | 11.777 es |
| Registration #3 | 11.777 es |
| Registration #4 | 11.117 au |

More info >

CarCheck.co.uk page 7/8



SV18KWL

report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 95% |
| Children | 80% |
| Pedestrian | 76% |
| Safety systems | 93% |
| Overall rating | 88% |
| Video | see crash video |



Dimensions & weight

| Width | 1895 mm |
|---------------------|---------|
| Height | 1475 mm |
| Length | 4936 mm |
| Wheel base | 2941 mm |
| Kerb weight | 1696 kg |
| Max. allowed weight | 2310 kg |

Additional information

| Fuel tank capacity | 55 I | |
|-----------------------------------|------------------|----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 8/8 |

Number of axles 2
Engine number 2363154