



General information

|                     |                        |
|---------------------|------------------------|
| Make                | FORD                   |
| Model               | MONDEO ZETEC 136PS     |
| Colour              | Grey                   |
| Year of manufacture | 2010                   |
| Top speed           | 124 mph                |
| 0 - 60 mph          | 9.6 seconds            |
| Gearbox             | 6 speed Semi-Automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 136 BHP             |
| Max. torque             | 319 Nm at 2.000 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 36.2 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 48.7 mpg            |
| CO2 emission            | 154 g/km            |
| CO2 label               | G                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-01-31                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: autoonline.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-06-15 |
| MOT pass rate      | 92 %       |
| MOT passed         | 12         |
| Failed MOT tests   | 1          |
| Total advice items | 23         |
| Total items failed | 1          |

|                  |   |
|------------------|---|
| MOT #13          | 2023-06-16 11:51  |
| MOT test number  | 971639744318  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-06-15  |
| Advice           | Sub-frame corroded but not seriously weakened Both front and rear sub frame and suspension components (5.3.3 (b) (i)) |

|                 |                  |
|-----------------|------------------|
| MOT #12         | 2022-05-19 13:43 |
| MOT test number | 775093577073     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #11         | 2021-06-03 15:38 |
| MOT test number | 266008636803     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #10         | 2020-10-28 17:51 |
| MOT test number | 106756016721     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #9          | 2020-03-09 10:07 |
| MOT test number | 678247494256     |
| Result          | ✓ Passed         |



|                 |                  |
|-----------------|------------------|
| MOT #8          | 2019-03-07 11:27 |
| MOT test number | 324442585234     |
| Result          | ✓ Passed         |
| MOT #7          | 2018-03-07 10:29 |
| MOT test number | 205497600421     |
| Result          | ✓ Passed         |
| MOT #6          | 2017-02-17 14:51 |
| MOT test number | 121840891408     |
| Result          | ✓ Passed         |



MOT #5

2016-03-03 10:17

MOT test number

142769552689

Result

✓ Passed

- Advice
- Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice
- Nearside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)
- Advice
- Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice
- Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)
- Advice
- Offside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice
- Nearside Rear coil spring corroded (2.4.C.1b)
- Advice
- Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice
- Exhaust system corroded
- Advice
- Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice
- Offside Front Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)
- Advice
- Nearside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice
- Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement starting to split from bonding (2.4.G.2)
- Advice
- Offside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)
- Advice
- Nearside Rear Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice
- Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)
- Advice
- Front Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice
- Front Inner brake discs pitted and corroded
- Advice
- Offside Rear coil spring corroded (2.4.C.1b)
- Advice
- Nearside Front Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)

**MOT #4** 2015-03-12 14:14**MOT test number** 469321475065**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-06 09:57**MOT test number** 285865164001**Result** ✓ Passed**MOT #2** 2014-03-06 09:57**MOT test number** 908035564060**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #1** 2013-03-09 09:30**MOT test number** 495078963087**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
15 June 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 January           |
| <b>Days left</b>        | 248                             |
| <b>MOT expiry date</b>  | 15 June 2024                    |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-09-29 |
| Current registration | *****      |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2010-03-12               |
| Last registration          | 2023-06-16               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2010-03-12 | 10 mi     |
| Registration #2  | 2013-03-09 | 21.424 mi |
| Registration #3  | 2014-03-06 | 26.249 mi |
| Registration #4  | 2015-03-12 | 29.352 mi |
| Registration #5  | 2016-03-03 | 33.518 mi |
| Registration #6  | 2017-02-17 | 39.311 mi |
| Registration #7  | 2018-03-07 | 50.300 mi |
| Registration #8  | 2019-03-07 | 55.377 mi |
| Registration #9  | 2020-03-07 | 55.377 mi |
| Registration #10 | 2021-03-07 | 55.377 mi |
| Registration #11 | 2022-03-07 | 55.377 mi |
| Registration #12 | 2023-03-07 | 55.377 mi |
| Registration #13 | 2024-03-07 | 55.377 mi |
| Registration #14 | 2025-03-07 | 55.377 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2019 mm |
| Height              | 1500 mm |
| Length              | 4337 mm |
| Wheel base          | 2640 mm |
| Max. allowed weight | 1950 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 53 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |

Engine number

AB89987