



VK57KPN

report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Silver
Year of manufacture	2007
Top speed	98 mph
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	159 Nm at 2.000 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	122 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-06-12
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-19
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	25
Total items failed	3

MOT #20	2024-03-14 10:14
MOT test number	888394407740
Result	✓ Passed
Next expiry date	2025-03-19
Advice	Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2023-03-20 07:13
MOT test number	477243948442
Result	✓ Passed
Advice	Rear Suspension component pin or bush slightly worn Axle beam bushes (both) (5.3.4 (a) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #18** 2023-03-15 08:07**MOT test number** 609580326366**Result** ✗ Failed**Advice** Rear Suspension component pin or bush slightly worn Axle beam bushes (both) (5.3.4 (a) (i))**MAJOR** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Exhaust has a major leak of exhaust gases Back box (6.1.2 (a))**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #17** 2022-03-02 13:36**MOT test number** 183181146649**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2022-03-02 11:02**MOT test number** 888437894786**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #15** 2021-02-26 07:42**MOT test number** 561245051898**Result** ✓ Passed

**MOT #14** 2020-03-18 16:30**MOT test number** 955491712078**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2019-03-26 12:25**MOT test number** 297137091922**Result** ✓ Passed**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive spring hangers (5.3.6 (a) (i))**MOT #12** 2019-03-26 12:25**MOT test number** 723596820594**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) all not working (4.3.1 (a) (iii))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive spring hangers (5.3.6 (a) (i))**MOT #11** 2018-03-23 12:31**MOT test number** 674315581204**Result** ✓ Passed**MOT #10** 2017-04-11 11:28**MOT test number** 230789801734**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit worn and cracking (4.1.E.1)

**MOT #9** 2016-04-21 08:46**MOT test number** 135328094386**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2016-04-20 10:17**MOT test number** 707309627377**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**MOT #7** 2015-04-14 11:31**MOT test number** 396314705132**Result** ✓ Passed**MOT #6** 2014-04-10 15:55**MOT test number** 366710204160**Result** ✓ Passed**MOT #5** 2013-04-08 13:04**MOT test number** 197038893075**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2012-04-13 11:37**MOT test number** 246654302404**Result** ✓ Passed



MOT #3	2011-04-20 11:29
MOT test number	995310411153
Result	✓ Passed
MOT #2	2011-04-20 11:29
MOT test number	236210611109
Result	✗ Failed
<div>Pass with rectification</div> Offside Headlamp aim too high (1.8)	
MOT #1	2010-09-15 09:00
MOT test number	122458250270
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 March 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	VK57KPN
Plate since	2019-03-29
Current registration	VK57KPN
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-21
Last registration	2024-03-14
Complete history	See info



Registration #1	2007-09-21	7 mi
Registration #2	2010-09-15	11.703 mi
Registration #3	2011-04-20	20.451 mi
Registration #4	2012-04-13	23.262 mi
Registration #5	2013-04-08	26.815 mi
Registration #6	2014-04-10	30.312 mi
Registration #7	2015-04-14	34.344 mi
Registration #8	2016-04-20	37.884 mi
Registration #9	2016-04-21	37.884 mi
Registration #10	2017-04-11	43.148 mi
Registration #11	2018-03-23	48.553 mi
Registration #12	2019-03-20	50.000 mi
Registration #13	2020-03-20	50.000 mi
Registration #14	2021-03-20	50.000 mi
Registration #15	2022-03-20	50.000 mi
Registration #16	2023-03-20	50.000 mi
Registration #17	2024-03-20	50.000 mi
Registration #18	2025-03-20	50.000 mi
Registration #19	2026-03-20	50.000 mi
Registration #20	2027-03-20	50.000 mi
Registration #21	2028-03-20	50.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

7Y06878