





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT 200 P/V
Colour	White
Year of manufacture	2015
Top speed	145 mph
0 - 60 mph	17.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	220 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-23

Pictures 15

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-05
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	13
Total items failed	14

MOT #11	2024-01-06 12:52
MOT test number	397177969680
Result	✓ Passed
Next expiry date	2025-01-05
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5 Advice Offside Front Tyre worn close to legal limit/worn on edge (5)	

мот #	10	2023-12-16 12:48
MOT to	est number	451489917811
Result		× Failed
Advi	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Mino	Registration plate lamp inoperative in the case of multiple lamps or light source	es (4.7.1 (b) (i))
Fail	Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advi	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advi	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Rear Brakes imbalanced across an axle (1.2.1 (b) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Minor
(i))

Advice

Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #8 2022-10-04 10:41 **MOT** test number 662715717675 Result × Failed Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i)) Fail **Advice** Front Inner Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e)) Fail Offside Front Tyre not fitted in accordance with side wall instructions rotation (5.2.3 (i)) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7	2021-09-27 10:54
MOT test number	252943320534
Result	✓ Passed
MOT #6	2021-09-27 10:54
MOT test number	800140157969
Result	★ Failed
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2020-12-09 13:12

MOT test number 139508301664

Result ✓ Passed

MOT #4 2020-12-08 09:46

MOT test number 475361828150

Result ★ Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Body component damaged and likely to cause injury door mirror casing damaged and jagged edges (6.2.1 (a) (i))

MOT #3 2019-11-29 09:15

MOT test number 117243770660

MOT #2 2018-12-07 15:15

MOT test number 655240403155

Result \(\sqrt{Passed} \)

MOT #1 2018-12-07 11:06

MOT test number 429087862499

Result X Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Brake hydraulic reservoir fluid level significantly below minimum level (1.1.10 (d) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	5 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have?

Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

faste since

See in this check if this FORD had different number plates.

ÜK

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-12-18
Last registration	2024-01-06
Complete history	See info



Registration #1	2015-12-18	20 mi
Registration #2	2018-12-07	29.738 mi
Registration #3	2018-12-07	29.739 mi
Registration #4	2019-11-29	39.967 mi
Registration #5	2020-12-08	47.747 mi
Registration #6	2020-12-09	47.768 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	85%
Pedestrian	62%
Safety systems	70%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2137 mm
Height	1861 mm
Length	4418 mm
Kerb weight	1380 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

FK28090