



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 SPORT DCI
Colour	Silver
Year of manufacture	2014
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	37.2 mpg
CO2 emission	190 g/km
CO2 label	J






Internet history

Entry 2


Date	2022-02-19
Pictures	21
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-21
Pictures	21
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-29
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	32
Total items failed	8

MOT #10	2023-12-22 08:43
MOT test number	526420327753
Result	✓ Passed
Next expiry date	2024-12-29
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Central Child Seat fitted not allowing full inspection of adult belt MIDDLE ROW
Advice	Nearside Front FOG LIGHT NOT WORKING
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt MIDDLE ROW

MOT #9	2022-12-30 14:30
MOT test number	188319237077
Result	✓ Passed

MOT #8	2022-12-30 14:30
MOT test number	489233110849
Result	✗ Failed
Pass with rectification	Front Headlamp aim too high (4.1.2 (a))

**MOT #7** 2022-04-04 08:41**MOT test number** 559508116976**Result** ✓ Passed

- Advice** Both rear trailing arm bushes covered in grease
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front discs (1.1.14 (a) (ii))

MOT #6 2021-08-26 07:37**MOT test number** 649075274471**Result** ✓ Passed

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Offside Seat belt webbing slightly damaged or frayed middle row (7.1.2 (b) (ii))

**MOT #5**

2021-08-10 13:00

MOT test number

813036326279

Result**✗ Failed**

- Fail** Seat belt damaged Nearside rear middle seat (7.1.2 (b) (i))
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Seat belt webbing slightly damaged or frayed offside middle rear seat belt (7.1.2 (b) (ii))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear brake pipe slight corroded (1.1.11 (c))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #4**

2020-08-17 13:28

MOT test number

957381587218

Result

✓ Passed

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Brake pipe corroded, covered in grease or other material Front - Rear brake pipes slight corroded (1.1.11 (c))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Seat belt slightly damaged Middle row seat belt (7.1.2 (b) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material Front - Rear brake pipes slight corroded (1.1.11 (c))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3**

2019-08-15 14:58

MOT test number

642888453619

Result

✓ Passed

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #2**

2018-09-03 08:11

MOT test number

730927490773

Result

✓ Passed

Advice Offside Rear Seat belt webbing slightly damaged or frayed middle row (7.1.2 (b) (ii))**MOT #1**

2017-09-21 15:27

MOT test number

287488697775

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
29 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	29 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-18
Last registration	2023-12-22
Complete history	See info



Registration #1	2014-09-18	29 mi
Registration #2	2017-09-21	75.994 mi
Registration #3	2018-09-03	98.992 mi
Registration #4	2019-08-15	125.172 mi
Registration #5	2020-08-17	141.991 mi
Registration #6	2021-08-10	160.154 mi
Registration #7	2021-08-26	160.154 mi
Registration #8	2022-05-22	160.154 mi
Registration #9	2022-05-22	160.154 mi
Registration #10	2022-05-22	160.154 mi
Registration #11	2022-05-22	160.154 mi
Registration #12	2022-05-22	160.154 mi
Registration #13	2022-05-22	160.154 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1954 mm
Length	5182 mm
Kerb weight	1907 kg
Max. allowed weight	3055 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2

Engine number

C116028