



**MP03E0V**


report date: 2024-03-29

General information

Make	JAGUAR
Model	XKR XKR CONVERTIBLE
Colour	Maroon
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	400 BHP
Max. torque	553 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.6 mpg
Consumption extra urban	30.7 mpg
Consumption combined	22.6 mpg
CO2 emission	304 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-12-16
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-12-14
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-25
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	45
Total items failed	14

MOT #18	2023-05-26 11:19
MOT test number	596330443814
Result	✓ Passed
Next expiry date	2024-05-25
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear nearside and offside plan in diff cups

MOT #17	2023-04-14 16:06
MOT test number	294169478754
Result	✗ Failed
Advice	Rear nearside and offside play in diff
Fail	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength subframe mounting (5.3.6 (a) (i))
Fail	Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill (6.1.1 (c) (i))
Advice	Rear Integral body structure is corroded but structural rigidity is not significantly reduced nearside and offside inner sill (6.1.1 (c) (i))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive subframe mounting (5.3.6 (a) (i))
Advice	Front Integral body structure is corroded but structural rigidity is not significantly reduced nearside and offside floorpan (6.1.1 (c) (i))

**MOT #16** 2022-04-13 15:42**MOT test number** 539234605496**Result** ✓ Passed

**Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

**MOT #15** 2021-05-08 14:48**MOT test number** 401622506046**Result** ✓ Passed**MOT #14** 2020-07-20 09:22**MOT test number** 131710311804**Result** ✓ Passed**MOT #13** 2019-07-24 13:55**MOT test number** 513524631015**Result** ✓ Passed**MOT #12** 2019-07-09 13:11**MOT test number** 417554102487**Result** ✗ Failed

**Fail** Nearside Rear Drive shaft joint excessively worn (6.1.7 (c) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))

**MOT #11** 2018-07-09 09:52**MOT test number** 983204440918**Result** ✓ Passed**MOT #10** 2017-07-13 15:43**MOT test number** 881291154854**Result** ✓ Passed**Advice** Nearside Rear Rear wheel bearing has slight play Felt play between disc and back plate (2.6.2)**Advice** Oil leak Rear diff oil leak**Advice** Steering column top bearing slightly worn (2.1.2c)**Advice** Oil leak Engine offside**MOT #9** 2017-07-13 15:43**MOT test number** 872428828665**Result** ✗ Failed**Advice** Oil leak Engine offside**Advice** Nearside Rear Rear wheel bearing has slight play Felt play between disc and back plate (2.6.2)**Pass with rectification** Central Brake clevis joint has restricted free movement (3.5.1k)**Pass with rectification** Rear registration plate insecure (6.3.1b)**Advice** Oil leak Rear diff oil leak**Advice** Steering column top bearing slightly worn (2.1.2c)



MOT #8	2016-07-13 07:24
MOT test number	413770508153
Result	✓ Passed
Advice	Nearside Rear wheel bearing has slight play (2.6.2)
Advice	Offside oil leak on engine
Advice	Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
Advice	Slight oil leak on steering rack input shaft
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
Advice	Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)
Advice	Oil leak on gearbox
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
Advice	Both front tyres feathering on inner edge

**MOT #7**

2016-07-12 14:58

**MOT test number**

925293251691

**Result****✗ Failed**

- Advice** Offside oil leak on engine
- Advice** Nearside Rear wheel bearing has slight play (2.6.2)
- Advice** Slight oil leak on steering rack input shaft
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Oil leak on gearbox
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Advice** Both front tyres feathering on inner edge
- Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)

**MOT #6**

2015-06-16 11:31

**MOT test number**

905487465118

**Result****✓ Passed**

- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #5** 2013-07-10 15:03**MOT test number** 756881393196**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Nearside Rear Drive shaft which forms part of the suspension support bearing slightly worn (2.4.G.4d)**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Offside Rear Drive shaft which forms part of the suspension support bearing slightly worn (2.4.G.4d)**MOT #4** 2012-06-20 11:03**MOT test number** 298082572142**Result** ✓ Passed**MOT #3** 2011-06-22 16:57**MOT test number** 976283171152**Result** ✓ Passed**MOT #2** 2011-06-21 15:24**MOT test number** 198692971192**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)





MOT #1	2010-06-03 12:19
MOT test number	564414950123
Result	✓ Passed
Notice	Offside front tyre low on inside edge
Notice	Slight play in both rear drive shaft inner universal joints
Notice	Slight damage on offside rear wheel rim
Notice	Corrosion on rear brake discs



Tax & MOT check

X

Untaxed

Tax expired:  
13 December 2021

✓

MOT

Expires:  
25 May 2024

Tax status	Expired at 13 December 2021
Days left	868 days too late
MOT expiry date	25 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-06-27
Last registration	2023-05-26
Complete history	<a href="#">See info</a>



Registration #1	2003-06-27	13 mi
Registration #2	2010-06-03	89.068 mi
Registration #3	2011-06-21	92.222 mi
Registration #4	2011-06-22	92.222 mi
Registration #5	2012-06-20	95.991 mi
Registration #6	2013-07-10	99.586 mi
Registration #7	2015-06-16	104.252 mi
Registration #8	2016-07-12	107.024 mi
Registration #9	2016-07-13	107.024 mi
Registration #10	2017-07-13	109.023 mi
Registration #11	2017-07-13	109.023 mi
Registration #12	2019-05-20	111.277 mi
Registration #13	2019-05-20	111.277 mi
Registration #14	2019-05-20	111.277 mi
Registration #15	2019-05-20	111.277 mi
Registration #16	2019-05-20	111.277 mi
Registration #17	2019-05-20	111.277 mi
Registration #18	2019-05-20	111.277 mi
Registration #19	2019-05-20	111.277 mi
Registration #20	2019-05-20	111.277 mi
Registration #21	2019-05-20	111.277 mi

More info >



Dimensions & weight

Width	2015 mm
Height	1306 mm
Length	4760 mm
Wheel base	2588 mm
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B0310010249