



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 DRIVE R-DESIGN START/STOP
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C



**MOT history**

MOT expiry date	2021-10-10
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #8	2020-09-16 11:59
MOT test number	496321702509
Result	✓ Passed
Next expiry date	2021-10-10
Advice	Offside Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7	2019-09-27 10:27
MOT test number	967308094688
Result	✓ Passed

MOT #6	2019-09-24 15:27
MOT test number	544992549663
Result	✗ Failed
MAJOR	Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
DANGEROUS	Offside Front Tyre has ply or cords exposed inside edge (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge approx 3mm (5.2.3 (e))
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inside edge wearing (5.2.3 (e))

**MOT #5** 2018-10-03 08:47**MOT test number** 629924485221**Result** ✓ Passed**MOT #4** 2017-09-12 09:30**MOT test number** 722641766436**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-09-13 11:11**MOT test number** 623804789418**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit both near the wear bars and wearing on the inside edge (4.1.E.1)**MOT #2** 2015-10-02 09:32**MOT test number** 470671943843**Result** ✓ Passed**MOT #1** 2014-09-26 11:50**MOT test number** 316159964417**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

X

Untaxed

Tax expired:
8 February 2021

X

MOT

Expired:
10 October 2021

Tax status	Expired at 8 February 2021
Days left	1176 days too late
MOT expiry date	10 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2011-10-10
Last registration	2020-09-16
Complete history	See info



Registration #1	2011-10-10	17 mi
Registration #2	2014-09-26	27.514 mi
Registration #3	2015-10-02	34.709 mi
Registration #4	2016-09-13	44.362 mi
Registration #5	2017-09-12	54.243 mi
Registration #6	2019-09-16	65.277 mi
Registration #7	2019-09-16	65.277 mi
Registration #8	2019-09-16	65.277 mi
Registration #9	2019-09-16	65.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Adult 94%

Children 82%

Pedestrian 64%

Safety systems 100%

Overall rating 86%

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1587 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4116932