





report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 280 CDI EDITION S
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L



CarCheck.co.uk page 1/14



Internet history

Entry 2

Date	2021-10-13

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-06
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-01-08
Mor expiry dute	2023 01 00
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	34
Total items failed	4

MOT #19		2024-01-08 13:46
MOT test	number	698030231198
Result		✓ Passed
Next expi	ry date	2025-01-08
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Non obligatory mirror damaged glass missing	

MOT #18		2022-12-13 11:53
MOT test	number	230956029336
Result		✓ Passed
Advice	Full underside inspection prevented by undertrays	
Advice	Offside running board damaged	
Advice	Rear wiper rubber incomplete	
Advice	Oil seepage	
Advice	Front tyres worn on both edges	
Advice	Offside repeater light damaged and condensated	
Advice	Nearside rear shock absorber damp	

CarCheck.co.uk page 3/14



Advice

J15TSA

report date: 2024-03-28

MOT #17 2022-12-12 14:38 **MOT** test number 276358662072 Result × Failed **Advice** Nearside rear shock absorber damp Advice Full underside inspection prevented by undertrays **MAJOR** Windscreen washer not working all (3.5 (a)) **MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii)) Advice Offside running board damaged **MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i)) Advice Rear wiper rubber incomplete Advice Oil seepage Advice Front tyres worn on both edges **MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii)) **MAJOR** Nearside Obligatory mirror does not provide a view to the rear (3.3 (c))

MOT #16	2021-12-15 09:34
MOT test number	689577075820
Result	. ✓ Passed

Offside repeater light damaged and condensated

MOT #15 2021-01-04 13:03

MOT test number 487895083448

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 4/14



Result

J15TSA report date: 2024-03-28

X Failed

MOT #14 2020-01-06 15:09
MOT test number 434601563224

Result \(\sqrt{Passed} \)

Advice Both rear tyres wearing on inner edges

MOT #13 2020-01-06 15:09

MOT test number 608161541752

Pass with rectification Nearside Rear Direction indicator not working (4.4.1 (a) (ii))

Advice Both rear tyres wearing on inner edges

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #12 2020-01-03 15:15

MOT test number 889489389778

Result × Failed

Advice Nearside Rear inner position lamp inop

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside upper stop lamp inop

MOT #11 2019-01-09 15:32

MOT test number 974336792831

Result \(\sqrt{Passed} \)

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 5/14



MOT #10 2019-01-09 11:14

MOT test number 216890250876

Result X Failed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #9 2018-01-06 09:43

MOT test number 728844817225

Result

Passed

MOT #8 2017-01-05 12:21

MOT test number 581456789665

Result ✓ Passed

MOT #7 2016-01-04 10:43

MOT test number 522159110833

MOT #6 2015-01-07 18:04

MOT test number 405237705078

Result ✓ Passed

MOT #5 2013-12-20 12:48

MOT test number 146924953397

Result ✓ Passed

MOT #4 2012-10-10 08:44

MOT test number 919864682247

CarCheck.co.uk page 6/14



MOT #3 2011-10-11 16:17

MOT test number 477324581272

MOT #2 2010-10-25 13:49

MOT test number 201678490218

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-10-25 13:49

MOT test number 842928290260

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Headlamp aim too low (1.8)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2

Date		
Category		

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK SIR
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-10-26
Last registration	2024-01-08
Complete history	See info



Registration #1	2007-10-26	11 mi
Registration #2	2010-10-25	45.139 mi
Registration #3	2011-10-11	54.331 mi
Registration #4	2012-10-10	64.028 mi
Registration #5	2013-12-20	72.338 mi
Registration #6	2015-01-07	76.099 mi
Registration #7	2016-01-04	78.846 mi
Registration #8	2017-01-05	79.325 mi
Registration #9	2018-01-06	83.830 mi
Registration #10	2019-01-09	91.870 mi
Registration #11	2019-01-09	91.870 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		9.377 mi

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg

Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	95 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040371305

CarCheck.co.uk page 14/14