





report date: 2024-03-29

General information

| Make | KIA |
|---------------------|---------------------|
| Model | VENGA 1 ECODYNAMICS |
| Colour | White |
| Year of manufacture | 2013 |
| Top speed | 103 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 137 Nm at 4.000 rpm |
| Engine capacity | 1.396 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 130 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

| E | n | tı | ry | 1 |
|---|---|----|----|----|
| | n | τı | ry | т. |

| Lifety 1 | |
|---------------|-------------|
| Date | 2021-03-07 |
| Pictures | 0 |
| Listing price | View report |

source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-04-24 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 16 |
| Total items failed | 3 |

| MOT #11 | | 2023-04-25 09:34 |
|-----------|---|------------------|
| MOT test | number | 102710370081 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-04-24 |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (| (1) |

| MOT #10 | | 2023-04-25 09:34 |
|--|---|------------------|
| MOT test | number | 146299290819 |
| Result | | × Failed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Pass wit | th rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c) |) |

CarCheck.co.uk page 3/12



report date: 2024-03-29

★ Failed

MOT #9

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

MOT test number

2021-03-26 16:18

244764460807

Result

✓ Passed

MOT #7 2021-03-22 15:57

MOT test number 559261087311

Fail Rear fog lamp not working (4.5.1 (a) (ii))

Result

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2020-10-21 07:36

MOT test number 133582556589

Result

Passed

MOT #5 2019-10-23 08:40

MOT test number 412811308925

Result

Passed

CarCheck.co.uk page 4/12



MOT #2

MOT test number

SO13FCU

report date: 2024-03-29

2016-10-28 14:38

331055578368

| MOT #4 | 2018-10-16 10:35 |
|--|------------------|
| MOT test number | 850574892149 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2017-10-16 09:25 |
| MOT test number | 682955652305 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |

| Result | ✓ Passed |
|-----------------|------------------|
| | |
| MOT #1 | 2016-06-06 11:59 |
| MOT test number | 640452506127 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



SO13FCU report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 1 |
| MOT expiry date | 24 April 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

| , | | |
|---|--|---|
| For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report | | |
| | | |
| | | |
| | | |
| | | |
| ******* | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this KIA had different number plates. | | |
| Number of plates | | |
| Current registration | NK NE | |
| Plate since | | |
| Current registration | OK ON THE STATE OF | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >


CarCheck.co.uk page 10/12



SO13FCU report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2013-06-17 |
| Last registration | 2023-04-25 |
| Complete history | See info |



| Registration #1 | 2013-06-17 | 20 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-06-06 | 11.055 mi |
| Registration #3 | 2016-10-28 | 12.917 mi |
| Registration #4 | 2017-10-16 | 19.877 mi |
| Registration #5 | 2018-10-16 | 27.863 mi |
| Registration #6 | 2019-10-23 | 35.214 mi |
| Registration #7 | 2020-10-21 | 43.199 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 ea |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 10.777 es |

More info >

CarCheck.co.uk page 11/12



SO13FCU report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 1765 mm |
|---------------------|---------|
| Height | 1600 mm |
| Length | 4068 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1343 kg |
| Max. allowed weight | 1710 kg |

Additional information

| Fuel tank capacity | 48 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

Number of axles 2

Engine number G4FADZ018734