



TOYOTA

NA07ZBJ


report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEAT
Colour	Black
Year of manufacture	2007
Top speed	109 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	410 Nm at 2.800 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L





## Internet history

### Entry 3

Date 2023-02-18

Pictures 24

Listing price [View report](#)



source: cargurus.co.uk

### Entry 2

Date 2023-02-17

Pictures 20

Listing price [View report](#)




source: autotrader.co.uk

### Entry 1

Date 2021-07-27

Pictures 31

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2023-08-09
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	33
Total items failed	24

MOT #20	2022-08-01 16:12
---------	------------------

MOT test number	408699855923
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-08-09
------------------	------------

- Advice

Heavy corrosion to suspension components, chassis and body
- Minor

Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Advanced corrosion around both central front body mounts
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Excessive corrosion around both central rear body mounts
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Excessive corrosion to nearside front inner wheel arch

**MOT #19**

2022-07-25 10:00

**MOT test number**

357144556637

**Result****✗ Failed****Minor**

Front Headlamp lens slightly defective Both cloudy/faded (4.1.1 (b) (i))

**Advice**

Excessive corrosion to nearside front inner wheel arch

**Fail**

Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice**

Advanced corrosion around both central front body mounts

**Fail**

Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Minor**

Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice**

Heavy corrosion to suspension components, chassis and body

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Nearside Rear Brake disc overheated

**Advice**

Excessive corrosion around both central rear body mounts

**MOT #18**

2021-08-10 14:10

**MOT test number**

476797217116

**Result****✓ Passed****MOT #17**

2021-08-07 12:13

**MOT test number**

797003867920

**Result****✗ Failed****Fail**

Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

**Fail**

Offside Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

**Fail**

Rear Exhaust has a major leak of exhaust gases box (6.1.2 (a))

**MOT #16**

2021-05-25 09:12

**MOT test number**

356521086532

**Result**

✓ Passed

**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #15**

2021-05-20 11:03

**MOT test number**

155194046926

**Result**

✗ Failed

**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Lower Suspension arm pin or bush excessively worn trailing arm rear bush (5.3.4 (a) (i))**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt inner boot (6.1.7 (g) (ii))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #14**

2019-10-11 08:59

**MOT test number**

763095692159

**Result**

✓ Passed

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Under body/suspension under sealed**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #13** 2018-09-24 11:42**MOT test number** 633031565572**Result** ✓ Passed**Advice** Underbody and chassis and all suspension parts all corroded**MOT #12** 2018-09-13 11:54**MOT test number** 897174610946**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Underbody and chassis and all suspension parts all corroded**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2017-10-20 13:55**MOT test number** 472665385521**Result** ✓ Passed**MOT #10** 2016-05-10 14:28**MOT test number** 970335428717**Result** ✓ Passed

**MOT #9** 2016-05-10 08:38**MOT test number** 823480754669**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2015-05-19 09:18**MOT test number** 388939735159**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2014-05-21 16:05**MOT test number** 638721444135**Result** ✓ Passed**MOT #6** 2014-05-20 09:20**MOT test number** 217740644184**Result** ✗ Failed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Front brake application uneven (3.7.B.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)

**MOT #5** 2013-05-15 14:44**MOT test number** 266985133436**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #4** 2012-05-14 17:19**MOT test number** 255945032144**Result** ✓ Passed**MOT #3** 2012-05-14 09:58**MOT test number** 399585932115**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #2** 2011-05-20 14:36**MOT test number** 336680641188**Result** ✓ Passed**MOT #1** 2010-05-27 09:42**MOT test number** 214297140422**Result** ✓ Passed





Tax & MOT check

✕  
Untaxed

Tax expired:  
3 February 2023

✕  
MOT

Expired:  
9 August 2023

Tax status	Expired at 3 February 2023
Days left	452 days too late
MOT expiry date	9 August 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-05-24
Last registration	2022-08-01
Complete history	<a href="#">See info</a>



Registration #1	2007-05-24	25 mi
Registration #2	2010-05-27	24.921 mi
Registration #3	2011-05-20	32.249 mi
Registration #4	2012-05-14	39.433 mi
Registration #5	2012-05-14	39.433 mi
Registration #6	2013-05-15	46.726 mi
Registration #7	2014-05-20	54.264 mi
Registration #8	2014-05-21	54.281 mi
Registration #9	2015-05-19	61.970 mi
Registration #10	2016-05-10	68.309 mi
Registration #11	2016-05-10	68.309 mi
Registration #12	2017-10-20	75.202 mi
Registration #13	2018-05-20	82.100 mi
Registration #14	2019-05-20	89.000 mi
Registration #15	2020-05-20	95.900 mi
Registration #16	2021-05-20	102.800 mi
Registration #17	2022-05-20	109.700 mi
Registration #18	2023-05-20	116.600 mi
Registration #19	2024-05-20	123.500 mi
Registration #20	2025-05-20	130.400 mi
Registration #21	2026-05-20	137.300 mi
Registration #22	2027-05-20	144.200 mi
Registration #23	2028-05-20	151.100 mi
Registration #24	2029-05-20	158.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4405 mm
Wheel base	2790 mm
Kerb weight	1990 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1624525