





report date: 2024-03-29

### General information

Make	JAGUAR
Model	XJ D V6 PORTFOLIO
Colour	Grey
Year of manufacture	2011
Top speed	155 mph
0 - 60 mph	6.0 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	271 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/14




# Internet history


### Entry 1

Date 2021-10-01


Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-08-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	36
Total items failed	0

MOT #14		2023-08-25 12:23	
MOT test i	number	392849505506	
Result		✓ Passed	
Next expi	ry date	2024-08-24	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))		
Advice	Rear Brake pad(s) wearing thin N/S inner + Both O/S (1.1.13 (a) (ii))		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Worn on inner ed	ge (5.2.3 (e))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (	5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner e	edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



(i))

AV11DBZ report date: 2024-03-29

MOT #13 2023-08-19 11:37

MOT test number 985224695525

Result **X** Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e)) Advice Rear Brake pad(s) wearing thin N/S inner + Both O/S (1.1.13 (a) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e)) Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e)) Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice **MAJOR** Nearside Rear Lower Suspension arm pin or bush excessively worn Inner rear rose bush (5.3.4 (a)

MOT #12 2022-08-15 11:49

MOT test number 882969561495

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

CarCheck.co.uk page 4/14



**AV11DBZ** 

report date: 2024-03-29

**MOT #11** 2022-07-08 14:28

**MOT test number** 243106493790

Result X Failed

**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

**MAJOR** Electronic parking brake warning indicates a malfunction (1.1.6 (e))

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Brake performance not tested (1.2.1 (g))

MOT #10 2021-06-29 08:23

MOT test number 616724694188

Advice Nearside Front Tyre worn close to legal limit/worn on edge both edges (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge both edges (5.2.3 (e))

CarCheck.co.uk page 5/14



MOT #9 2021-06-28 14:13

**MOT test number** 766075620645

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge both edges (5.2.3 (e))

**MAJOR** Electronic parking brake control inoperative (1.1.6 (d))

Advice Nearside Front Tyre worn close to legal limit/worn on edge both edges (5.2.3 (e))

**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**MAJOR** Offside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii))

MOT #8 2020-07-03 14:43

**MOT test number** 347527335379

Result \( \sqrt{Passed} \)

**MOT #7** 2019-09-16 08:32

**MOT test number** 990035147305

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2018-09-19 08:49

**MOT test number** 403876851327

Result \( \sqrt{Passed} \)

**MOT #5** 2017-09-16 10:43

MOT test number 419205168831

**Result** 
✓ Passed

CarCheck.co.uk page 6/14



MOT #4	2016-09-16 09:08
MOT test number	243366300928
Result	<b>✓</b> Passed
MOT #3	2015-09-18 08:12
MOT test number	247525787485
Result	<b>✓</b> Passed
MOT #2	2014-09-24 15:53
MOT test number	925097364234
Result	<b>✓</b> Passed
MOT #1	2014-03-28 15:44
MOT test number	867737084020
Result	✓ Passed

CarCheck.co.uk page 7/14



### Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	24 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



## Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
********	
***************************************	
********	
************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	EK UK
Plate since	
Current registration	UK NIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 12/14



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-28
Last registration	2023-08-25
Complete history	See info



Registration #1	2011-03-28	15 mi
Registration #2	2014-03-28	30.259 mi
Registration #3	2014-09-24	34.185 mi
Registration #4	2015-09-18	45.875 mi
Registration #5	2016-09-16	56.828 mi
Registration #6	2017-09-16	68.032 mi
Registration #7	2018-09-19	74.827 mi
Registration #8	2019-09-16	79.972 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 13/14



		_		
- I ) Im	ension	с Х.	WAIG	nt.
	CHSIUH	3 W	weiu	III.

Width	2110 mm
Height	1448 mm
Length	5247 mm
Wheel base	3157 mm
Kerb weight	1796 kg
Max. allowed weight	2365 kg

## Additional information

Fuel tank capacity	83 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	0467140306DT

CarCheck.co.uk page 14/14