





report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD ES
Colour	Blue
Year of manufacture	2001
Top speed	124 mph
0 - 60 mph	10.1 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	178 Nm at 4.800 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	20.2 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.2 mpg
CO2 emission	235 g/km
CO2 label	L



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-09-16

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-04-24
MOT pass rate	95 %
MOT passed	18
Failed MOT tests	1
Total advice items	17
Total items failed	1
MOT #19	2023-04-13 15:57
MOT test number	416178416208
Result	✓ Passed
Next expiry date	2024-04-24
MOT #18	2022-04-25 12:22
MOT test number	915474975052
Result	✓ Passed

MOT #17	2021-03-31 08:01
MOT test number	876808239553
Result	✓ Passed

MOT #16	2020-03-26 10:03
MOT test number	838625637435
Result	✓ Passed

CarCheck.co.uk page 3/14



Result

Y961VKJreport date: 2024-03-29

× Failed

MOT #15 2019-03-18 15:19

MOT test number 125220669768

Minor Offside Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Fuel Pipe/s corroded

Minor Nearside Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14 2018-03-23 08:03

MOT test number 446352706061

Result ✓ Passed

MOT #13 2018-03-22 09:03

MOT test number 416415256675

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Fail Offside Front Anti-roll bar linkage insecure (2.4.G.1)

MOT #12 2017-04-05 15:51

MOT test number 718146065507

Result

Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2016-04-06 15:16

MOT test number 315047197948

Result
✓ Passed

CarCheck.co.uk page 4/14



MOT #10	2015-03-10 09:05
MOT test number	108909165463
Result	✓ Passed
MOT #9	2014-03-06 09:09
MOT test number	895725364085
Result	✓ Passed
MOT #8	2013-03-13 12:49
MOT test number	376222673048
Result	✓ Passed
MOT #7	2012-03-06 12:00
MOT test number	697386262056
Result	✓ Passed
MOT #6	2011-03-14 11:03
MOT test number	816073371002
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)	

CarCheck.co.uk page 5/14



MOT #5 2010-03-09 14:32

MOT test number 362868160053

Result Passed

Advice Front Exhaust has part of the system slightly deteriorated (7.1.1a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear brake disc slightly pitted (3.5.1h)

Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc slightly pitted (3.5.1h)

Advice Centre Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #4 2009-03-10 11:52

MOT test number 103239669043

Result \(\sqrt{Passed} \)

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #3 2008-03-11 13:28

MOT test number 684141178051

Result ✓ Passed

MOT #2 2007-03-08 16:10

MOT test number 994507567064

Result ✓ Passed

CarCheck.co.uk page 6/14



MOT #1 2006-03-02 15:54

MOT test number 624931366071

Result ✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	24 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2001-03-14
Last registration	2023-04-13
Complete history	See info



Registration #1	2001-03-14	6 mi
Registration #2	2006-03-02	33.287 mi
Registration #3	2007-03-08	39.819 mi
Registration #4	2008-03-11	44.706 mi
Registration #5	2009-03-10	51.203 mi
Registration #6	2010-03-09	56.191 mi
Registration #7	2011-03-14	62.818 mi
Registration #8	2012-03-06	68.541 mi
Registration #9	2013-03-13	72.705 mi
Registration #10	2014-03-06	75.984 mi
Registration #11	2015-03-10	80.249 mi
Registration #12		11.777 es
Registration #13		D.702 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1785 mm
Length	4767 mm
Kerb weight	1325 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	F20B71000403

CarCheck.co.uk page 14/14