



RENAULT

WI78MDB

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE SCENIC ALIZE
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	90 BHP
Max. torque	131 Nm at 2.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg





Internet history

Entry 1

Date	2021-07-10
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #22	2021-03-25 11:15
MOT test number	881039722851
Result	✓ Passed
Next expiry date	2022-04-01
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Outer sills corroded
Advice	Nearside Front sill holed not within perscribed area

MOT #21	2021-03-24 11:17
MOT test number	922694949934
Result	✗ Failed
Fail	Brake performance not tested (1.2.1 (g))
Advice	Outer sills corroded
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Rear Brake pipe leaking on an air braking system behind exhaust heat shield (1.1.11 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front sill holed not within perscribed area
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2020-03-18 15:56
MOT test number	802637317881
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #19**

2019-03-05 10:51

MOT test number

732366289886

Result

✓ Passed

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases rear silencer (6.1.2 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #18**

2018-03-12 11:43

MOT test number

123911471971

Result

✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #17**

2018-03-10 14:47

MOT test number

521879636795

Result

✗ Failed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Horn not working (1.6.2a)

**MOT #16** 2017-03-08 10:52**MOT test number** 863668341702**Result** ✓ Passed

- Advice** Surface corrosion to n/s sill
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear wiper blade split
- Advice** Surface corrosion to rear wheel arches

MOT #15 2016-03-16 09:59**MOT test number** 237799473823**Result** ✓ Passed

- Advice** Corrosion to rear arch
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #14 2015-03-07 14:49**MOT test number** 146366665461**Result** ✓ Passed

- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13** 2015-03-04 11:04**MOT test number** 676723365098**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2014-03-18 13:30**MOT test number** 188307574492**Result** ✓ Passed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2013-03-11 10:16**MOT test number** 428260773052**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Corrosion to rear crossbar

**MOT #10** 2012-04-02 16:01**MOT test number** 535003192095**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #9** 2011-03-07 11:42**MOT test number** 506986561066**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Slight binnding to o/s/r brake**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #8** 2011-03-07 11:42**MOT test number** 215036461062**Result** ✗ Failed**Notice** Slight binnding to o/s/r brake**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #7** 2010-03-09 16:13**MOT test number** 923898160079**Result** ✓ Passed**MOT #6** 2010-03-09 16:13**MOT test number** 174188360071**Result** ✗ Failed**Pass with rectification** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2009-03-21 11:57**MOT test number** 712210189072**Result** ✓ Passed**MOT #4** 2009-03-21 10:08**MOT test number** 591710989014**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Registration plate lamp not working (1.1.5c)**MOT #3** 2008-03-20 14:19**MOT test number** 114930188487**Result** ✓ Passed**MOT #2** 2007-03-20 10:24**MOT test number** 852299577022**Result** ✓ Passed**MOT #1** 2006-03-22 14:42**MOT test number** 802501186001**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2000-03-30
Last registration	2021-03-25
Complete history	See info



Registration #1	2000-03-30	27 mi
Registration #2	2006-03-22	26.475 mi
Registration #3	2007-03-20	30.664 mi
Registration #4	2008-03-20	34.915 mi
Registration #5	2009-03-21	39.146 mi
Registration #6	2009-03-21	39.146 mi
Registration #7	2010-03-09	43.011 mi
Registration #8	2011-03-07	51.583 mi
Registration #9	2012-04-02	62.303 mi
Registration #10	2013-03-11	71.431 mi
Registration #11	2014-03-18	80.861 mi
Registration #12	2015-03-22	91.277 mi
Registration #13	2016-03-22	101.277 mi
Registration #14	2017-03-22	111.277 mi
Registration #15	2018-03-22	121.277 mi
Registration #16	2019-03-22	131.277 mi
Registration #17	2020-03-22	141.277 mi
Registration #18	2021-03-22	151.277 mi
Registration #19	2022-03-22	161.277 mi
Registration #20	2023-03-22	171.277 mi
Registration #21	2024-03-22	181.277 mi
Registration #22	2025-03-22	191.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★ ★ ★ ★ ★

Video [see crash video](#)



Dimensions & weight

Width	1940 mm
Height	1417 mm
Length	3818 mm
Wheel base	2472 mm
Kerb weight	965 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	DA46154