



report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ TDVI SOVEREIGN LWB
Colour	Blue
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-28
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-06
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	20
Total items failed	11

MOT #20	2024-01-05 17:51
MOT test number	507833966991
Result	✓ Passed
Next expiry date	2025-01-06

MOT #19	2024-01-03 15:02
MOT test number	119011880450
Result	✗ Failed
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #18	2023-01-07 12:17
MOT test number	556147792211
Result	✓ Passed

MOT #17	2023-01-05 09:24
MOT test number	920682190445
Result	✗ Failed
Fail	Nearside Rear Lower Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #16** 2021-12-02 16:21**MOT test number** 612727910562**Result** ✓ Passed**MOT #15** 2020-12-01 09:23**MOT test number** 650345536119**Result** ✓ Passed**MOT #14** 2019-12-05 08:57**MOT test number** 894142318680**Result** ✓ Passed**MOT #13** 2018-11-22 17:32**MOT test number** 555736571877**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #12** 2017-11-27 12:24**MOT test number** 265352610114**Result** ✓ Passed**Advice** Offside Exhaust has a minor leak of exhaust gases cat (7.1.2)**Advice** Nearside Front Radius arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Exhaust has a minor leak of exhaust gases cat (7.1.2)**Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Offside Front Radius arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #11** 2016-12-05 15:12**MOT test number** 309047482421**Result** ✓ Passed**Advice** Nearside Exhaust has a minor leak of exhaust gases between turbo and cat (7.1.2)**Advice** Nearside Front Radius arm rubber bush deteriorated but not resulting in excessive movement front round (2.4.G.2)**Advice** Offside Exhaust has a minor leak of exhaust gases between turbo and cat (7.1.2)**Advice** Offside Front Radius arm rubber bush deteriorated but not resulting in excessive movement front round (2.4.G.2)**MOT #10** 2015-11-26 11:41**MOT test number** 729317498549**Result** ✓ Passed**MOT #9** 2014-11-21 10:54**MOT test number** 315915024398**Result** ✓ Passed**MOT #8** 2013-11-27 16:54**MOT test number** 779941933372**Result** ✓ Passed**MOT #7** 2013-10-01 12:56**MOT test number** 498014873275**Result** ✓ Passed

**MOT #6** 2013-09-30 12:42**MOT test number** 956063073232**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**MOT #5** 2012-10-11 17:02**MOT test number** 537565582262**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-10-11 10:45**MOT test number** 837635482293**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2011-10-10 09:41**MOT test number** 285773881214**Result** ✓ Passed



MOT #2	2010-10-15 13:16
MOT test number	692998980200
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-10-27 16:20
MOT test number	253680209357
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
6 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	6 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>MF57DXD</b>
Plate since	2024-03-29
Current registration	<b>MF57DXD</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-07
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2007-09-07	26 mi
Registration #2	2009-10-27	18.477 mi
Registration #3	2010-10-15	41.477 mi
Registration #4	2011-10-10	50.919 mi
Registration #5	2012-10-11	63.415 mi
Registration #6	2012-10-11	63.415 mi
Registration #7	2013-09-30	73.179 mi
Registration #8	2013-10-01	73.181 mi
Registration #9	2013-11-27	73.608 mi
Registration #10	2014-11-21	75.838 mi
Registration #11	2015-11-26	78.168 mi
Registration #12	2016-01-20	80.500 mi
Registration #13	2016-02-20	82.833 mi
Registration #14	2016-03-20	85.166 mi
Registration #15	2016-04-20	87.500 mi
Registration #16	2016-05-20	89.833 mi
Registration #17	2016-06-20	92.166 mi
Registration #18	2016-07-20	94.500 mi
Registration #19	2016-08-20	96.833 mi
Registration #20	2016-09-20	99.166 mi
Registration #21	2016-10-20	101.500 mi
Registration #22	2016-11-20	103.833 mi

More info >



Dimensions & weight

Width	1898 mm
Height	1455 mm
Length	5215 mm
Wheel base	3159 mm
Kerb weight	1659 kg
Max. allowed weight	2306 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	02230647G