





report date: 2024-03-29

### General information

Make	MERCEDES
Model	E E270 CDI ELEGANCE
Colour	Silver
Year of manufacture	2004
Top speed	142 mph
0 - 60 mph	8.4 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	177 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.685 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	41.5 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2024-12-19
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	38
Total items failed	3

MOT #20	2023-12-18 12:37
MOT test number	325617683007
Result	✓ Passed
Next expiry date	2024-12-19
Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	

2022-12-20 14:21
719630318587
✓ Passed
•

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT test number

Result

Pass with rectification

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number
626666397494

Result

Advice
Nearside headlamp light output slightly reduced

Advice
Brake pipe corroded, covered in grease or other material nearside & offside front to rear (1.1.11 (c))

Advice
Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

MOT test number

Result

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

CarCheck.co.uk page 3/13



**MOT #14** 2019-01-31 10:01

**MOT test number** 972183772967

**Result** X Failed

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail Offside Direction indicator not working mirror indicator inop (4.4.1 (a) (ii))

**MOT #13** 2018-02-06 16:45

**MOT test number** 296365037328

**Result** ✓ Passed

**Advice** Oil leak

**Advice** All four tyres wearing inner edges

**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #12** 2017-02-04 12:24

**MOT test number** 293011227494

**Result** 
✓ Passed

**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Stop lamp has light sources not illuminating, but not more than 50% Centre (1.2.1b)

**MOT #11** 2016-01-22 10:13

**MOT test number** 777611554328

**MOT #10** 2015-08-12 12:15

**MOT test number** 640183989927

CarCheck.co.uk page 4/13



MOT #9 2014-08-22 07:10

**MOT test number** 129784234242

**Result** ✓ Passed

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Notice** Play in steering rack inner joint(s)

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #8 2013-08-27 12:25

MOT test number 177849433293

**Result** ✓ Passed

MOT #7 2012-12-07 14:21

**MOT test number** 539172342325

**Result** ✓ Passed

**Advice** Offside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)

**Notice** Front brake pipes corroded

MOT #6 2011-12-12 13:31

**MOT test number** 419806541372

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Front brake pipes slightly corroded

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #5 2011-12-12 11:44

**MOT test number** 319916441349

Result X Failed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Rear brake discs worn/scored

**Notice** Rear tyre pressures low

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Front brake pipes slightly corroded

MOT #4 2010-12-13 13:51

**MOT test number** 133767740318

**Result** ✓ Passed

MOT #3 2009-11-18 09:25

**MOT test number** 460022229375

**Result** ✓ Passed

**MOT #2** 2008-11-12 09:03

**MOT test number** 551467218397

**Result** 
✓ Passed

**MOT #1** 2007-11-24 08:52

**MOT test number** 592018627356

**Result** 
✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	19 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Type Type

Damage 2

Category

Date

Туре



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	m.o.o
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In kilometers	
Mileage registrations	21	
First mileage registration	2004-12-03	
Last registration	2023-12-18	
Complete history	See info	



Registration #1	2004-12-03	14 mi
Registration #2	2007-11-24	10.156 mi
Registration #3	2008-11-12	14.267 mi
Registration #4	2009-11-18	16.341 mi
Registration #5	2010-12-13	19.552 mi
Registration #6	2011-12-12	28.130 mi
Registration #7	2011-12-12	28.130 mi
Registration #8	2012-12-07	41.300 mi
Registration #9	2013-08-27	46.965 mi
Registration #10	2014-08-22	50.912 mi
Registration #11	2015-08-12	63.764 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		

More info >

CarCheck.co.uk page 12/13



Dimensions &	weig	ht
--------------	------	----

Width	1980 mm
Height	1440 mm
Length	4818 mm
Wheel base	2833 mm
Kerb weight	1665 kg

# Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	64796130101352

CarCheck.co.uk page 13/13