



General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Blue
Year of manufacture	2006
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 2



Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	11
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-11-13
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	39
Total items failed	6

MOT #19 2023-11-14 14:27

MOT test number 322617621295

Result ✓ Passed

Next expiry date 2024-11-13

- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Front Play in steering rack inner joint(s)
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18 2022-11-01 11:22

MOT test number 343556187541

Result ✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive spring hanger (5.3.6 (a) (i))

**MOT #17**

2021-11-01 13:11

MOT test number

692522670878

Result

✓ Passed

Advice Offside Rear Outer Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #16

2020-10-26 12:23

MOT test number

556499649450

Result

✓ Passed

Advice Suspension arm pin or bush worn but not resulting in excessive movement Both front rear wishbone bushes (5.3.4 (a) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Brake disc worn, but not excessively Both front (1.1.14 (a) (i))

Advice Surface corrosion on vehicle underbody/both sil's front to rear

Advice Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))

MOT #15

2019-05-02 12:34

MOT test number

880384077315

Result

✓ Passed

MOT #14

2019-04-30 15:58

MOT test number

824596610948

Result

✗ Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #13** 2018-07-13 08:36**MOT test number** 308679505636**Result** ✓ Passed**MOT #12** 2017-07-17 09:15**MOT test number** 428882144519**Result** ✓ Passed**MOT #11** 2016-07-20 09:33**MOT test number** 895711800467**Result** ✓ Passed**Advice** Offside Front tyre wearing inner edge**Advice** Nearside Front tyre wearing inner edge**MOT #10** 2015-07-28 15:08**MOT test number** 398099505400**Result** ✓ Passed**MOT #9** 2014-09-30 17:24**MOT test number** 338603374274**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2014-09-30 17:24**MOT test number** 717973674252**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)

**MOT #7** 2013-10-01 08:56**MOT test number** 548104573212**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Central stop lamp not working**MOT #6** 2012-10-05 11:46**MOT test number** 385589072276**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Air bag light on**MOT #5** 2012-10-05 11:46**MOT test number** 328599772273**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Air bag light on**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2011-10-06 14:18**MOT test number** 425319471248**Result** ✓ Passed**Notice** Seat belts 6 and 7 not checked, seats down.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.D.4)**Notice** Screenwash bottle lid missing**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-07-21 15:59**MOT test number** 653392700261**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #2** 2010-07-21 15:59**MOT test number** 951542300274**Result** ✓ Passed**MOT #1** 2009-08-10 14:03**MOT test number** 482882229238**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	FL56BZA
Plate since	2024-03-28
Current registration	FL56BZA
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-29
Last registration	2023-11-14
Complete history	See info



Registration #1	2006-09-29	25 mi
Registration #2	2009-08-10	41.402 mi
Registration #3	2010-07-21	51.426 mi
Registration #4	2011-10-06	65.316 mi
Registration #5	2012-10-05	75.900 mi
Registration #6	2013-10-01	85.245 mi
Registration #7	2014-09-30	98.902 mi
Registration #8	2015-07-28	10.899 mi
Registration #9	2016-07-20	114.155 mi
Registration #10	2017-07-17	119.974 mi
Registration #11	2018-06-20	121.377 mi
Registration #12	2019-06-20	121.377 mi
Registration #13	2020-06-20	121.377 mi
Registration #14	2021-06-20	121.377 mi
Registration #15	2022-06-20	121.377 mi
Registration #16	2023-06-20	121.377 mi
Registration #17	2024-06-20	121.377 mi
Registration #18	2025-06-20	121.377 mi
Registration #19	2026-06-20	121.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	6R35775