



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Black
Year of manufacture	2008
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-27
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	30
Total items failed	23

MOT #23	2023-12-05 12:59
MOT test number	957402771657
Result	✓ Passed
Next expiry date	2024-12-07
Advice	Rear Subframe bushes perished
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2022-12-08 17:16
MOT test number	844018385159
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #21**

2022-12-08 17:15

**MOT test number**

608721949473

**Result**

✗ Failed

**Pass with rectification** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Offside Side repeater not working (4.4.1 (a) (ii))**Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #20**

2021-10-07 12:46

**MOT test number**

154052938191

**Result**

✓ Passed

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19**

2021-09-30 15:20

**MOT test number**

453495074487

**Result**

✗ Failed

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Exhaust system insecure (6.1.2 (a))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

**MOT #18** 2021-01-15 11:14**MOT test number** 776630673382**Result** ✓ Passed**MOT #17** 2021-01-13 13:25**MOT test number** 559208470910**Result** ✗ Failed**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #16** 2020-01-08 12:55**MOT test number** 945421539222**Result** ✓ Passed**MOT #15** 2020-01-08 12:55**MOT test number** 587086231392**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #14** 2019-01-08 12:45**MOT test number** 169519150450**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #13**

2019-01-07 16:32

**MOT test number**

203408535381

**Result**

✗ Failed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear on limit (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**MOT #12**

2018-01-10 12:57

**MOT test number**

148310207653

**Result**

✓ Passed

**Advice** Oil leak**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Undertrays fitted**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**MOT #11**

2018-01-05 11:40

**MOT test number**

855967561413

**Result**

✗ Failed

**Advice** Oil leak**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Undertrays fitted

**MOT #10** 2016-08-31 10:32**MOT test number** 193978588864**Result** ✓ Passed**MOT #9** 2016-08-31 10:32**MOT test number** 479478573956**Result** ✗ Failed**Pass with rectification** Nearside Headlamp adversely affected by the operation of another lamp (1.7.5c)**MOT #8** 2015-08-22 10:39**MOT test number** 874129207697**Result** ✓ Passed**MOT #7** 2015-08-22 10:39**MOT test number** 786093746631**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #6** 2014-08-20 14:48**MOT test number** 806022534273**Result** ✓ Passed**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-08-20 14:48**MOT test number** 278052334266**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high and too far to the right. (1.8)**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Pass with rectification** Nearside Front Headlamp aim too high and too far to the left. (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-08-19 11:17**MOT test number** 237031934284**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Offside Front front brake binding (3.7.B.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Headlamp aim too high and too far to the right. (1.8)**MOT #3** 2013-08-21 16:17**MOT test number** 206913433232**Result** ✓ Passed**MOT #2** 2012-09-04 16:39**MOT test number** 278628942268**Result** ✓ Passed**Notice** Cuts on n/s/f tyre on outer wall





MOT #1	2011-08-31 13:11
MOT test number	677963441209
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
7 December 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	7 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>VA08EUU</b>
Plate since	2019-06-29
Current registration	<b>VA08EUU</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-08-14
Last registration	2023-12-05
Complete history	<a href="#">See info</a>



Registration #1	2008-08-14	27 mi
Registration #2	2011-08-31	15.558 mi
Registration #3	2012-09-04	22.529 mi
Registration #4	2013-08-21	29.909 mi
Registration #5	2014-08-19	41.788 mi
Registration #6	2014-08-20	41.788 mi
Registration #7	2015-08-22	48.993 mi
Registration #8	2015-08-22	48.993 mi
Registration #9	2016-08-31	55.506 mi
Registration #10	2016-08-31	55.506 mi
Registration #11	2018-01-05	59.785 mi
Registration #12	2018-01-10	59.785 mi
Registration #13	2018-01-10	59.785 mi
Registration #14	2018-01-10	59.785 mi
Registration #15	2018-01-10	59.785 mi
Registration #16	2018-01-10	59.785 mi
Registration #17	2018-01-10	59.785 mi
Registration #18	2018-01-10	59.785 mi
Registration #19	2018-01-10	59.785 mi
Registration #20	2018-01-10	59.785 mi
Registration #21	2018-01-10	59.785 mi
Registration #22	2018-01-10	59.785 mi
Registration #23	2018-01-10	59.785 mi
Registration #24	2018-01-10	59.785 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3



Number of seats	4
Number of axles	2
Engine number	BMD 395263