





report date: 2024-03-29

#### General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Grey
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/9



# MOT history

MOT expiry date	2021-11-30
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	7
Total items failed	7

MOT #5	2020-11-20 16:14
MOT test number	133806649451
Result	✓ Passed
Next expiry date	2021-11-30

MOT #4	2020-11-20 10:58
MOT test number	472543446881
Result	<b>X</b> Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (i	ii))
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.	.7.1 (b) (ii))

MOT #3		2019-05-31 17:03
MOT test	number	928566985196
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

CarCheck.co.uk page 2/9



2019-05-31 09:31 **MOT #2** 513412807137 **MOT** test number Result × Failed Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail **Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) **Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

MOT #1	2018-02-03 10:38
MOT test number	130728570575
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/9



#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 4/9



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 5/9



Owner	I
INMAR	nictory
	IIISLUIV

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.  More info >  Plate changes  See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.		More info >
器 UK  UK	Plate changes	
THE REPORT OF THE PROPERTY OF	See in this check if this CITROEN had different number plates.	
THE REPORT OF THE PROPERTY OF	Number of plates	,
Plate since	Current registration	UK SIES
Plate since	Plate since	
More info >	Current registration	NK SIN
More info >	Plate since	
		More info >

CarCheck.co.uk page 6/9



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 7/9



## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2015-01-16
Last registration	2020-11-20
Complete history	See info



Registration #1	2015-01-16	23 mi
Registration #2	2018-02-03	66.273 mi
Registration #3	2019-05-31	84.149 mi
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		0.77

More info >

CarCheck.co.uk page 8/9



## Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



## Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

## Additional information

Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961

CarCheck.co.uk page 9/9