



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-17
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history****MOT #16** 2022-06-14 13:52**MOT test number** 808724373277**Result** ✓ Passed**Next expiry date** 2023-06-15**Advice** Fuel tank exhaust shield loose but secure**Advice** Exhaust has a minor leak of exhaust gases Blowing from front of rear silencer (6.1.2 (a))**MOT #15** 2022-06-14 12:33**MOT test number** 230796283136**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps Rear registration plate lamps both sides not working (4.7.1 (b) (ii))**Advice** Exhaust has a minor leak of exhaust gases Blowing from front of rear silencer (6.1.2 (a))**Advice** Fuel tank exhaust shield loose but secure**MOT #14** 2021-06-16 11:20**MOT test number** 135482537505**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2021-06-15 16:49**MOT test number** 462209515752**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #12**

2020-05-26 13:11

**MOT test number**

184492199520

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #11**

2020-05-26 11:17

**MOT test number**

233943948690

**Result**

✗ Failed

- Fail** Offside Rear Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #10**

2019-05-31 14:25

**MOT test number**

863925762156

**Result**

✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre slightly out of shape on inner edge
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Exhaust heatshield loose where fitted as original equipment but not creating a risk of fire

**MOT #9** 2019-05-31 09:06**MOT test number** 588368844932**Result** ✗ Failed

- Fail** Nearside Front Seat belt not functioning as intended (7.1.2 (c))
- Advice** Rear Exhaust heatshield loose where fitted as original equipment but not creating a risk of fire
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Nail in tyre And slightly out of shape on inner edge
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2018-05-18 10:43**MOT test number** 929011632960**Result** ✓ Passed

**MOT #7** 2017-06-05 15:59**MOT test number** 496614451134**Result** ✓ Passed

- Advice** Tyre worn close to the legal limit ALL 4 (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside (3.5.1i)

**MOT #6** 2017-06-05 15:59**MOT test number** 580487805553**Result** ✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside (3.5.1i)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Tyre worn close to the legal limit ALL 4 (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

**MOT #5** 2016-04-05 13:14**MOT test number** 887225375993**Result** ✓ Passed

- Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2015-03-10 17:13**MOT test number** 118539065402**Result** ✓ Passed**Notice** Slight run flat damage to offside front tyre**MOT #3** 2014-03-07 11:50**MOT test number** 517046864069**Result** ✓ Passed**MOT #2** 2013-03-05 12:43**MOT test number** 686064863027**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-09-04 09:51**MOT test number** 226618742293**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-10
Last registration	2022-06-14
Complete history	<a href="#">See info</a>



Registration #1	2009-11-10	14 mi
Registration #2	2012-09-04	30.401 mi
Registration #3	2013-03-05	36.944 mi
Registration #4	2014-03-07	47.588 mi
Registration #5	2015-03-10	58.707 mi
Registration #6	2016-04-05	64.448 mi
Registration #7	2017-06-05	76.224 mi
Registration #8	2017-06-05	76.224 mi
Registration #9	2018-05-18	83.965 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607