



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO VALVEMATIC TR
Colour	Blue
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G



**MOT history**

MOT expiry date	2024-06-25
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	36
Total items failed	3

MOT #12 2023-06-26 08:32**MOT test number** 197070717937**Result** Passed**Next expiry date** 2024-06-25

- Minor** Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #11 2021-12-30 12:39**MOT test number** 614289866343**Result** Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #10 2020-11-05 13:19**MOT test number** 647830243494**Result** Passed

**MOT #9** 2020-11-05 13:19**MOT test number** 862660871765**Result** ✗ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8 2019-05-21 08:47**MOT test number** 447500745484**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin BOTH SIDES (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDES (1.1.14 (a) (ii))

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated BOTH SIDES (5.3.4 (b) (i))

MOT #7 2018-04-24 14:45**MOT test number** 494220122354**Result** ✓ Passed

Advice Offside Rear Lamp damaged

Advice Offside Rear Bumper insecure

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.2b)

MOT #6 2017-04-24 14:56**MOT test number** 576608606826**Result** ✓ Passed**MOT #5** 2016-04-21 12:06**MOT test number** 109975887611**Result** ✓ Passed

**MOT #4**

2015-03-27 11:27

MOT test number

767176185033

Result

✓ Passed

Advice Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice N/S/R Tyre damaged due to underinflation and perished

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Under-trays fitted obscuring some underside components

Notice O/S/R Tyre perished

MOT #3

2014-04-17 10:44

MOT test number

427737004178

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Front brake discs worn/lipped

Notice ALL 4 Tyres perished. Some splitting in tread area

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Notice Rear wiper blade has no blade

Notice Rear bumper damaged

Advice Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)



MOT #2 2014-04-17 10:44

MOT test number 215767504458

Result ✗ Failed

Notice ALL 4 Tyres perished. Some splitting in tread area

Advice Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

Notice Rear wiper blade has no blade

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Rear bumper damaged

Pass with rectification Body has a sharp edge caused by damage (6.1.C.1)

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Notice Front brake discs worn/lipped

MOT #1 2013-04-10 15:58

MOT test number 769720103182

Result ✓ Passed

Notice 3rd row of seats in closed position

Notice Nail in nearside rear tyre



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GY10LMK
Plate since	2019-09-29
Current registration	GY10LMK
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-04-09
Last registration	2023-06-26
Complete history	See info



Registration #1	2010-04-09	24 mi
Registration #2	2013-04-10	16.377 mi
Registration #3	2014-04-17	24.964 mi
Registration #4	2015-03-27	34.263 mi
Registration #5	2016-04-21	40.846 mi
Registration #6	2017-04-24	43.002 mi
Registration #7	2018-05-29	55.277 mi
Registration #8	2019-05-29	55.277 mi
Registration #9	2020-05-29	55.277 mi
Registration #10	2021-05-29	55.277 mi
Registration #11	2022-05-29	55.277 mi
Registration #12	2023-06-26	55.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

2ZFU254814