





report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 SPORT HDI
Colour	Silver
Year of manufacture	2006
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-25

Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



KB06PWF
report date: 2024-03-29

MOT history

MOT expiry date	2024-08-07
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	43
Total items failed	8

MOT #24	2023-08-08 13:26
MOT test number	290356105795
Result	✓ Passed
Next expiry date	2024-08-07
Advice Offside Play in steering rack inner joint(s)	

MOT #23		2023-08-01 16:03
MOT test i	number	869429972967
Result		X Failed
Advice	Offside Play in steering rack inner joint(s)	
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR the ingress	Offside Front Outer Drive shaft joint constant velocity boot split or insecure of dirt (6.1.7 (g) (ii))	, no longer prevents
MAJOR	Fuel system component leaking from fuel additive tank (6.1.3 (b) (i))	
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #22	2022-07-26 09:37
MOT test number	218801366849
Result	✓ Passed
Advice Covers obscuring some components	

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #21 2022-07-22 14:08

MOT test number 984262449215

Result X Failed

MAJOR Offside Front Seat belt damaged (7.1.2 (b) (i))

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Covers obscuring some components

MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))

MOT #20 2021-06-18 11:40

MOT test number 343898318304

Result
✓ Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19 2021-06-17 15:18

MOT test number 694118932274

Result × Failed

MAJOR Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #18 2020-08-20 16:42

MOT test number 571198873883

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #17

MOT test number

178979752724

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2019-06-12 08:18 **MOT** test number 411291551135 Result × Failed **MAJOR** Nearside Steering rack has excessive free play detected at the steering wheel (steering rack fitted) rack arm (2.3 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) **MAJOR MAJOR** Offside Front Suspension rod pin or bush excessively worn drop link (5.3.4 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

MOT test number

Result

Advice

Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice

Offside Front Anti-roll bar linkage has slight play in a pin bearing (2.4.G.2)

Advice

Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #14

MOT test number

546896885768

Result

Advice Play in both rack ends

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit splitting (4.1.E.1)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Fail

Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice

Play in both rack ends

MOT #12		2016-05-09 07:46
MOT test number		607382785516
Result		√ Passed
MOT #11		2016-05-09 07:46
MOT test number		931435346095
Result		X Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Pass with rectification	Offside Headlamp aim too low (1.8)	

MOT #10	2016-02-05 10:08
MOT test number	130303548067
Result	✓ Passed
Advice Under tray fitted	

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT test number

Result

Advice Under tray fitted

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

MOT test number

S29326925052

Result

Notice Front brake discs lipped

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #7

MOT test number

135851834400

Result

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #6

MOT test number

688599633054

Result

Notice Undertray fitted

MOT #5

MOT test number

Result

Notice Undertray fitted

2012-02-06 15:43

345987432027

Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #4	2012-02-06 11:01
MOT test number	997117332006
Result	× Failed
Notice Undertray fitted	
Fail Offside Rear position lamp(s) not working (1.1.A.3b)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Notice Front brake discs lipped and corroded	
Fail Offside Registration plate lamp not working (1.1.C.1d)	

MOT #3	2011-02-02 11:00
MOT test number	289433431047
Result	✓ Passed
MOT #2	2010-02-15 16:35
MOT test number	932896340077
Result	✓ Passed

MOT #1		2009-08-27 12:12
MOT test	number	671759539275
Result		✓ Passed
Advice	Front brake disc slightly scored (3.5.1h)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

0,44000	hictor.
Owner	nisioiv

		_
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		
THE STATE OF THE S		

	More info >	
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-08-18
Last registration	2023-08-08
Complete history	See info



Registration #1	2006-08-18	10 mi
Registration #2	2009-08-27	24.949 mi
Registration #3	2010-02-15	25.509 mi
Registration #4	2011-02-02	30.010 mi
Registration #5	2012-02-06	35.066 mi
Registration #6	2012-02-06	35.066 mi
Registration #7	2013-02-08	40.658 mi
Registration #8	2014-01-31	46.104 mi
Registration #9	2015-01-26	51.647 mi
Registration #10	2016-02-05	56.815 mi
Registration #11	2016-02-05	56.815 mi
Registration #12	2016-05-09	56.891 mi
Registration #13	2016-05-09	56.891 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		10,700 esi
Registration #26		71.777 es

CarCheck.co.uk page 14/15



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1653 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 15/2

Number of axles 2

Engine number DYVD4045610