



PEUGEOT



ND6IXKX


report date: 2024-03-29

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Black
Year of manufacture	2012
Top speed	132 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	38.7 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-16
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	20
Total items failed	2

MOT #14	2024-02-02 10:33
MOT test number	967795425028
Result	✓ Passed
Next expiry date	2025-02-16
Advice	Oil leak
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged sidewall damage and wearing inner edge (5.2.3 (d) (ii))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #13	2023-02-17 16:55
MOT test number	366315192363
Result	✓ Passed

**MOT #12**

2023-02-16 10:14

**MOT test number**

890092462978

**Result****✗ Failed**

- Advice** Oil leak, but not excessive engine area (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords outer side wall (5.2.3 (d) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged outer side wall (5.2.3 (d) (ii))

**MOT #11**

2022-12-07 15:20

**MOT test number**

683097579125

**Result****✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread and sidewall cracking bad (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords cuts sidewall (5.2.3 (d) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing tread cracking (5.2.3 (d) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Both front jacking points damaged
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))



<b>MOT #10</b>	2021-12-16 14:57
----------------	------------------

<b>MOT test number</b>	487302391102
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2021-03-04 10:11
---------------	------------------

<b>MOT test number</b>	558937863671
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2020-07-30 09:41
---------------	------------------

<b>MOT test number</b>	296385054932
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2019-08-02 09:02
---------------	------------------

<b>MOT test number</b>	705315846409
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2018-08-09 15:35
---------------	------------------

<b>MOT test number</b>	194778411769
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2018-01-31 12:26
---------------	------------------

<b>MOT test number</b>	260392064192
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2018-01-31 10:40
---------------	------------------

<b>MOT test number</b>	517934947971
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Headlamp insecure (1.7.3)
-------------	------------------------------------



MOT #3	2017-01-26 10:47
MOT test number	822618491829
Result	✓ Passed
MOT #2	2015-12-31 14:21
MOT test number	296195438115
Result	✓ Passed
MOT #1	2015-01-24 13:40
MOT test number	335194325021
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
16 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	16 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	ND61XKX
Plate since	2024-03-29
Current registration	ND61XKX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-01-30
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2012-01-30	22 mi
Registration #2	2015-01-24	10.657 mi
Registration #3	2015-12-31	14.082 mi
Registration #4	2017-01-26	17.730 mi
Registration #5	2018-01-31	18.915 mi
Registration #6	2018-01-31	18.915 mi
Registration #7	2018-08-09	19.339 mi
Registration #8	2019-08-02	21.524 mi
Registration #9	2019-08-02	21.524 mi
Registration #10	2019-08-02	21.524 mi
Registration #11	2019-08-02	21.524 mi
Registration #12	2019-08-02	21.524 mi
Registration #13	2019-08-02	21.524 mi
Registration #14	2019-08-02	21.524 mi
Registration #15	2019-08-02	21.524 mi
Registration #16	2019-08-02	21.524 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1372 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	FJBW1358549