



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO GTD
Colour	Green
Year of manufacture	2010
Top speed	138 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-08-27
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-26
Pictures	32
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-07
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	14
Total items failed	6

MOT #14	2023-10-04 10:35
MOT test number	540903456718
Result	✓ Passed
Next expiry date	2024-10-07

MOT #13	2022-10-08 09:19
MOT test number	953718682825
Result	✓ Passed
Advice	Osr/nsr tyres worn in inner edges/have cracking on inner an outer edges
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear registration plate lamp inoperative
Advice	Rear parking brake effort only just met
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12** 2022-10-08 08:22**MOT test number** 402641393259**Result** ✗ Failed**Advice** Rear parking brake effort only just met**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Osr/nsr tyres worn in inner edges/have cracking on inner an outer edges**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear registration plate lamp inoperative**MOT #11** 2021-09-13 15:02**MOT test number** 272407729424**Result** ✓ Passed**MOT #10** 2021-09-10 13:12**MOT test number** 455845357312**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))**MOT #9** 2020-09-07 13:22**MOT test number** 256800121708**Result** ✓ Passed

**MOT #8** 2020-09-02 09:12**MOT test number** 340666611054**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #7** 2019-03-26 11:19**MOT test number** 420538970473**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-03-28 09:20**MOT test number** 262508054987**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit tyre has 3mm of tread... legal limit is 1.6mm (4.1.E.1)**Advice** Lower under floor trays fitted**MOT #5** 2017-03-25 11:21**MOT test number** 587957755305**Result** ✓ Passed**MOT #4** 2016-03-07 09:54**MOT test number** 583197144851**Result** ✓ Passed



MOT #3	2015-04-01 09:41
MOT test number	828181895042
Result	✓ Passed
MOT #2	2014-03-12 12:10
MOT test number	249571274056
Result	✓ Passed
MOT #1	2013-04-15 14:54
MOT test number	208505403401
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
7 October 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	7 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>ML10TXW</b>
Plate since	2019-09-29
Current registration	<b>ML10TXW</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-10
Last registration	2023-10-04
Complete history	<a href="#">See info</a>



Registration #1	2010-05-10	15 mi
Registration #2	2013-04-15	18.456 mi
Registration #3	2014-03-12	22.355 mi
Registration #4	2015-04-01	35.897 mi
Registration #5	2016-03-07	47.418 mi
Registration #6	2017-03-25	56.049 mi
Registration #7	2018-03-28	64.660 mi
Registration #8	2019-03-26	73.296 mi
Registration #9	2020-09-02	82.737 mi
Registration #10	2021-05-20	91.277 mi
Registration #11	2022-05-20	99.277 mi
Registration #12	2023-05-20	107.277 mi
Registration #13	2024-05-20	115.277 mi
Registration #14	2025-05-20	123.277 mi
Registration #15	2026-05-20	131.277 mi
Registration #16	2027-05-20	139.277 mi
Registration #17	2028-05-20	147.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CFG 121854