





report date: 2024-03-29

### General information

Make	VOLKSWAGEN
Model	GOLF S TSI
Colour	Grey
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/12




## Internet history

#### Entry 1

Date 2021-06-06


Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-30
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	14
Total items failed	0

MOT #12		2023-08-31 12:07
MOT test	number	808472207385
Result		✓ Passed
Next exp	iry date	2024-08-30
Minor (i))	Nearside Registration plate lamp missing in the case of multiple lamps or lig	ht sources (4.7.1 (b)
Advice	Front Tyre worn close to legal limit/worn on edge X 2 (5.2.3 (e))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	l (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread Cracks (0	.1 (b))

MOT #11	2022-06-07 14:31
MOT test number	128237306691
Result	✓ Passed
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #10	2021-06-18 15:25
MOT test number	453690729524
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #9 2020-10-07 09:16

**MOT test number** 495833784245

Advice Nearside Rear Tyre starting to get low on tread

MOT #8 2019-10-14 11:04

MOT test number 636818261292

Result \( \sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-10-11 08:40

MOT test number 621282693652

Result 

Passed

Advice Rear Lower Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

MOT #6 2017-09-21 08:06

**MOT test number** 293983707800

Result \( \sqrt{Passed} \)

Advice Rear Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement both droplink lower bushes (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2016-10-12 13:35

MOT test number 400123303264

Result 

Passed

CarCheck.co.uk page 4/12



MOT #4 2015-10-08 15:03 **MOT test number** 174760497885 Result ✓ Passed 2014-10-14 16:41 MOT #3 **MOT test number** 857867084201 Result ✓ Passed MOT #2 2014-01-02 13:22 509512404051 **MOT test number** Result ✓ Passed MOT #1 2013-01-03 11:42 499523403096 **MOT test number** Result ✓ Passed **Notice** Vehicle's internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	30 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



**GV59YVL** 

report date: 2024-03-29

$\overline{}$	ner	L : _	L
()\\\	ner	nıs	rorv

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many volkswagen have? Check it in the premium report and see all owner registrations. Dow here.	
********	
*********	
***************************************	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK ZIS
Plate since	
Current registration	NK AIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



**GV59YVL** 

report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-01-08
Last registration	2023-08-31
Complete history	See info



Registration #1	2010-01-08	13 mi
Registration #2	2013-01-03	22.299 mi
Registration #3	2014-01-02	28.326 mi
Registration #4	2014-10-14	34.267 mi
Registration #5	2015-10-08	42.475 mi
Registration #6	2016-10-12	52.322 mi
Registration #7	2017-09-21	63.360 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.177 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1215 kg
Max. allowed weight	1850 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChack co.uk	page 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CAX 290226