



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Red
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-01-21
Pictures	29
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2023-01-25
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	20
Total items failed	17

MOT #11	2022-01-25 13:28
MOT test number	148986482642
Result	✓ Passed
Next expiry date	2023-01-25

MOT #10	2022-01-25 13:28
MOT test number	306875584200
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9	2021-01-26 16:48
MOT test number	727072904789
Result	✓ Passed

MOT #8	2021-01-26 16:48
MOT test number	808888508928
Result	✗ Failed
Pass with rectification	Offside Front Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification	Nearside Front Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))



MOT #7

2019-07-08 10:37

MOT test number

830734803479

Result

✓ Passed

- Advice

Offside Rear Nail in tyre
- Advice

Rear Exhaust mounting defective (6.1.2 (a))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Front Exhaust mounting defective (6.1.2 (a))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #6**

2019-07-05 15:09

MOT test number

231579581870

Result**✗ Failed**

- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5

2017-09-08 10:31

MOT test number

985649512012

Result**✓ Passed**

- Advice** Nearside Front suspension has slight movement at a wishbone pin or bush rearmost bush (2.5.A.1c)
- Advice** Offside Front suspension has slight movement at a wishbone pin or bush rearmost bush (2.5.A.1c)

**MOT #4** 2017-09-08 09:04**MOT test number** 669741732209**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front suspension has slight movement at a wishbone pin or bush rearmost bush (2.5.A.1c)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Front suspension has slight movement at a wishbone pin or bush rearmost bush (2.5.A.1c)**MOT #3** 2016-03-11 16:37**MOT test number** 657283624771**Result** ✓ Passed**Advice** Nearside front suspension arm rear bush split**MOT #2** 2016-03-11 13:09**MOT test number** 914538048802**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside front suspension arm rear bush split**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2015-03-11 13:13**MOT test number** 668550675006**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	BT12CUG
Plate since	2019-03-29
Current registration	BT12CUG
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-25
Last registration	2022-01-25
Complete history	See info



Registration #1	2012-06-25	23 mi
Registration #2	2015-03-11	64.232 mi
Registration #3	2016-03-11	74.889 mi
Registration #4	2016-03-11	74.889 mi
Registration #5	2017-09-08	84.591 mi
Registration #6	2017-09-08	84.593 mi
Registration #7	2019-07-05	89.600 mi
Registration #8	2020-01-25	95.277 mi
Registration #9	2020-01-25	95.277 mi
Registration #10	2020-01-25	95.277 mi
Registration #11	2020-01-25	95.277 mi
Registration #12	2020-01-25	95.277 mi
Registration #13	2022-01-25	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEJ3085743