



TOYOTA



report date: 2024-03-29

General information

| | |
|---------------------|------------------------------|
| Make | TOYOTA |
| Model | LAND CRUISER D-4D INVINCIBLE |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 109 mph |
| 0 - 60 mph | 11.2 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 171 BHP |
| Max. torque | 410 Nm at 1.800 rpm |
| Engine capacity | 2.982 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 24.4 mpg |
| Consumption extra urban | 37.7 mpg |
| Consumption combined | 31.4 mpg |
| CO2 emission | 238 g/km |
| CO2 label | L |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-01-11 |
| Pictures | 20 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-24 |
| MOT pass rate | 79 % |
| MOT passed | 15 |
| Failed MOT tests | 4 |
| Total advice items | 45 |
| Total items failed | 7 |

MOT #19 2023-11-07 11:53

MOT test number 689261953485

Result ✓ Passed

Next expiry date 2024-11-24

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))
- Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** General corrosion suspension

MOT #18 2022-11-25 08:58

MOT test number 119501860689

Result ✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2021-11-15 15:38**MOT test number** 189732670803**Result** ✓ Passed**MOT #16** 2021-01-04 10:10**MOT test number** 161388143115**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on the edges (5.2.3 (e))**MOT #15** 2020-12-16 16:13**MOT test number** 447080905977**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on the edges (5.2.3 (e))**MAJOR** Exhaust has a major leak of exhaust gases Rear box has a hole in (6.1.2 (a))**MOT #14** 2019-06-07 15:04**MOT test number** 203171004004**Result** ✓ Passed**Advice** Offside Rear Seat belt slightly damaged Back seat (7.1.2 (b) (i))**MOT #13** 2018-06-28 13:05**MOT test number** 360919925552**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Seat belt slightly damaged rear o/s boot seat (7.1.2 (b) (i))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2017-07-06 12:11**MOT test number** 762172264054**Result** ✓ Passed**Advice** Front both tyre worn on the edges**Advice** Nearside Rear tyre perished**Advice** Rear tyre worn on the edge**MOT #11** 2017-03-07 09:28**MOT test number** 820137272996**Result** ✓ Passed**Advice** All tyres worn on edges**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Engine covers and undertrays fitted**Advice** General corrosion**MOT #10** 2016-03-02 10:17**MOT test number** 140797205717**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit on edge - tread stepped (4.1.E.1)**Advice** Both rear tyres worn on edges**Advice** Offside Front Upper Brake pipe slightly corroded (3.6.B.2c)**Advice** Engine cover and under trays fitted**Advice** Nearside Front Upper Brake pipe slightly corroded (3.6.B.2c)

**MOT #9**

2016-03-01 10:48

MOT test number

927978097462

Result**✗ Failed****Advice** Both rear tyres worn on edges**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Upper Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit on edge - tread stepped (4.1.E.1)**Advice** Engine cover and under trays fitted**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Front Upper Brake pipe slightly corroded (3.6.B.2c)**MOT #8**

2015-03-10 10:54

MOT test number

938159365063

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7**

2014-03-07 13:11

MOT test number

918416064032

Result**✓ Passed****Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2014-03-03 10:59**MOT test number** 147162864027**Result** ✗ Failed**Fail** Offside Rear Rear fog lamp not working (1.3.2b)**Fail** Nearside Rear Rear fog lamp not working (1.3.2b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-02-18 10:01**MOT test number** 405249843096**Result** ✓ Passed**MOT #4** 2012-02-15 11:18**MOT test number** 757286742040**Result** ✓ Passed**Notice** Front brake discs slightly pitted**MOT #3** 2011-02-11 14:07**MOT test number** 875662841090**Result** ✓ Passed**Notice** Front discs pitted

**MOT #2**

2011-02-11 09:20

MOT test number

616782541033

Result**✗ Failed**

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Notice Front discs pitted

Fail Offside Rear Rear fog lamp not working (1.3.2b)

Fail Nearside Rear Rear fog lamp not working (1.3.2b)

MOT #1

2010-02-25 11:07

MOT test number

461946050045

Result**✓ Passed**

Advice Front brake disc slightly pitted (3.5.1h)

Notice Front tyres wearing on edges



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
24 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 246 |
| MOT expiry date | 24 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | L |
| Single payment (12 months) | £ 675,00,- |
| Single six month payment | £ 371,25,- |
| Total payable by 12 monthly instalments | £ 708,75,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | WV07OZX |
| Plate since | 2019-03-29 |
| Current registration | WV07OZX |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2007-03-05 |
| Last registration | 2023-11-07 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-03-05 | 15 mi |
| Registration #2 | 2010-02-25 | 22.753 mi |
| Registration #3 | 2011-02-11 | 26.627 mi |
| Registration #4 | 2011-02-11 | 26.627 mi |
| Registration #5 | 2012-02-15 | 27.519 mi |
| Registration #6 | 2013-02-18 | 29.541 mi |
| Registration #7 | 2014-03-03 | 32.299 mi |
| Registration #8 | 2014-03-07 | 32.301 mi |
| Registration #9 | 2015-03-10 | 33.686 mi |
| Registration #10 | 2016-03-01 | 35.979 mi |
| Registration #11 | 2016-03-02 | 35.979 mi |
| Registration #12 | 2016-03-02 | 35.979 mi |
| Registration #13 | 2016-03-02 | 35.979 mi |
| Registration #14 | 2016-03-02 | 35.979 mi |
| Registration #15 | 2016-03-02 | 35.979 mi |
| Registration #16 | 2016-03-02 | 35.979 mi |
| Registration #17 | 2016-03-02 | 35.979 mi |
| Registration #18 | 2016-03-02 | 35.979 mi |
| Registration #19 | 2016-03-02 | 35.979 mi |
| Registration #20 | 2016-03-02 | 35.979 mi |
| Registration #21 | 2016-03-02 | 35.979 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1875 mm |
| Height | 1905 mm |
| Length | 4850 mm |
| Wheel base | 2790 mm |
| Max. allowed weight | 2850 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 8 |
| Number of axles | 2 |
| Engine number | 1KD1617275 |